

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>7 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Yakima County</td> </tr> <tr> <td>Bridge Name:</td> <td>MEYERS ROAD NORTH #485</td> </tr> <tr> <td>Intersecting:</td> <td>YAKIMA RIVER</td> </tr> <tr> <td>Strudture ID:</td> <td>08478500</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>46° 24' 0" N</td> </tr> <tr> <td>Longitude:</td> <td>120° 16' 48" W</td> </tr> <tr> <td>Requester:</td> <td>Gene Soules @ (509) 574-2324</td> </tr> </table>	Sufficiency Rating:	7 SD	Bridge Owner Name:	Yakima County	Bridge Name:	MEYERS ROAD NORTH #485	Intersecting:	YAKIMA RIVER	Strudture ID:	08478500	Federal Highway:	On	Latitude:	46° 24' 0" N	Longitude:	120° 16' 48" W	Requester:	Gene Soules @ (509) 574-2324	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$9,218,050.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>12/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td>10/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$9,218,050.00	Preliminary Engineering:	12/1/2001	Right of Way:	10/1/2002	Construction Start:	6/1/2003								
Sufficiency Rating:	7 SD																																				
Bridge Owner Name:	Yakima County																																				
Bridge Name:	MEYERS ROAD NORTH #485																																				
Intersecting:	YAKIMA RIVER																																				
Strudture ID:	08478500																																				
Federal Highway:	On																																				
Latitude:	46° 24' 0" N																																				
Longitude:	120° 16' 48" W																																				
Requester:	Gene Soules @ (509) 574-2324																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$9,218,050.00																																				
Preliminary Engineering:	12/1/2001																																				
Right of Way:	10/1/2002																																				
Construction Start:	6/1/2003																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>485</td> </tr> <tr> <td>Deck:</td> <td>8</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>3</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>8</td> <td></td> </tr> <tr> <td>Scour:</td> <td>N</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>9</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>15</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	485	Deck:	8		Superstructure:	3		Substructure:	8		Scour:	N		Inventory Rating:	9	HS-20 (Tons)	Operating Rating:	15	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>3</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>9</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	3	Deck Geometry:	2	Under Clearance:	9	Wate way:	9	Roadway Alignment:	8	Safe Load Capacity:	5	
Condition Codes:	BridgeNo:	485																																			
Deck:	8																																				
Superstructure:	3																																				
Substructure:	8																																				
Scour:	N																																				
Inventory Rating:	9	HS-20 (Tons)																																			
Operating Rating:	15	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	3																																				
Deck Geometry:	2																																				
Under Clearance:	9																																				
Wate way:	9																																				
Roadway Alignment:	8																																				
Safe Load Capacity:	5																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>07</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>2 05</td> <td>1 01</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>6780</td> <td>1994</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>8</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1947</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>1</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>5</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	07	Main/Appr Material Design:	2 05	1 01	Average Daily Traffic Year:	6780	1994	Detour Length (Miles)	8		Year Built and Rebuilt:	1947	0	Historical Significance:	1		Open/Closed/Posted:	P		Number of Utilities:	5		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>468</td> </tr> <tr> <td>Curb to Curb:</td> <td>24</td> </tr> <tr> <td>Square feet of deck::</td> <td>11232</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>36</td> </tr> </table>	Geometric Data:		Bridge Length:	468	Curb to Curb:	24	Square feet of deck::	11232	Number of lanes on:	2	Approach Roadway Width:	36
Age and Service Data:	Fed Func Class:	07																																			
Main/Appr Material Design:	2 05	1 01																																			
Average Daily Traffic Year:	6780	1994																																			
Detour Length (Miles)	8																																				
Year Built and Rebuilt:	1947	0																																			
Historical Significance:	1																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	5																																				
Geometric Data:																																					
Bridge Length:	468																																				
Curb to Curb:	24																																				
Square feet of deck::	11232																																				
Number of lanes on:	2																																				
Approach Roadway Width:	36																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Multi-span Prestressed Concrete</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Piers and Abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Drilled Shafts</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove and replace existing bridge with a new bridge at current standards.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Multi-span Prestressed Concrete	New Sub Type:	Concrete Piers and Abutments	New Foundn Type:	Drilled Shafts	Proposed work:		Remove and replace existing bridge with a new bridge at current standards.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>26880</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$781,704.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$20,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$5,211,360.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$2,345,112.00</td> </tr> <tr> <td>Approach:</td> <td>\$859,874.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	26880	Preliminary Engineering:	\$781,704.00	Right of Way:	\$20,000.00	Construction:	\$5,211,360.00	Other Projected Costs:	\$2,345,112.00	Approach:	\$859,874.00										
Agency Replacement Comments:																																					
New Super Type:	Multi-span Prestressed Concrete																																				
New Sub Type:	Concrete Piers and Abutments																																				
New Foundn Type:	Drilled Shafts																																				
Proposed work:																																					
Remove and replace existing bridge with a new bridge at current standards.																																					
Agency Replacement Costs:																																					
New Square Foot:	26880																																				
Preliminary Engineering:	\$781,704.00																																				
Right of Way:	\$20,000.00																																				
Construction:	\$5,211,360.00																																				
Other Projected Costs:	\$2,345,112.00																																				
Approach:	\$859,874.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>GOOD</td> <td>POOR</td> <td>GOOD</td> <td>POOR</td> </tr> </table>		Technical Committee Comment		Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	GOOD	POOR	GOOD	POOR																								
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	GOOD	POOR	GOOD	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>10.99 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>SEATTLE</td> </tr> <tr> <td>Bridge Name:</td> <td>FREMONT BR. APPROACHES</td> </tr> <tr> <td>Intersecting:</td> <td>RR/ACCESS RD/PARKING LOT</td> </tr> <tr> <td>Strudture ID:</td> <td>08528200</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>49° 0' 0" 0"</td> </tr> <tr> <td>Longitude:</td> <td>124° 0' 0" 0"</td> </tr> <tr> <td>Requester:</td> <td>Richard Miller, P.E. @ (206) 684-5300</td> </tr> </table>	Sufficiency Rating:	10.99 SD	Bridge Owner Name:	SEATTLE	Bridge Name:	FREMONT BR. APPROACHES	Intersecting:	RR/ACCESS RD/PARKING LOT	Strudture ID:	08528200	Federal Highway:	On	Latitude:	49° 0' 0" 0"	Longitude:	124° 0' 0" 0"	Requester:	Richard Miller, P.E. @ (206) 684-5300	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$20,500,000.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2003</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2007</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$20,500,000.00	Preliminary Engineering:	6/1/2003	Right of Way:		Construction Start:	6/1/2007								
Sufficiency Rating:	10.99 SD																																				
Bridge Owner Name:	SEATTLE																																				
Bridge Name:	FREMONT BR. APPROACHES																																				
Intersecting:	RR/ACCESS RD/PARKING LOT																																				
Strudture ID:	08528200																																				
Federal Highway:	On																																				
Latitude:	49° 0' 0" 0"																																				
Longitude:	124° 0' 0" 0"																																				
Requester:	Richard Miller, P.E. @ (206) 684-5300																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$20,500,000.00																																				
Preliminary Engineering:	6/1/2003																																				
Right of Way:																																					
Construction Start:	6/1/2007																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>12A</td> </tr> <tr> <td>Deck:</td> <td>5</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>4</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>5</td> <td></td> </tr> <tr> <td>Scour:</td> <td>N</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>17</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>28</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	12A	Deck:	5		Superstructure:	4		Substructure:	5		Scour:	N		Inventory Rating:	17	HS-20 (Tons)	Operating Rating:	28	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>3</td> </tr> <tr> <td>Deck Geometry:</td> <td>4</td> </tr> <tr> <td>Under Clearance:</td> <td>3</td> </tr> <tr> <td>Wate way:</td> <td>9</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>4</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	3	Deck Geometry:	4	Under Clearance:	3	Wate way:	9	Roadway Alignment:	8	Safe Load Capacity:	4	
Condition Codes:	BridgeNo:	12A																																			
Deck:	5																																				
Superstructure:	4																																				
Substructure:	5																																				
Scour:	N																																				
Inventory Rating:	17	HS-20 (Tons)																																			
Operating Rating:	28	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	3																																				
Deck Geometry:	4																																				
Under Clearance:	3																																				
Wate way:	9																																				
Roadway Alignment:	8																																				
Safe Load Capacity:	4																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>17</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>0 00</td> <td>2 04</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>33100</td> <td>1993</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>3</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1917</td> <td>1927</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>B</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	17	Main/Appr Material Design:	0 00	2 04	Average Daily Traffic Year:	33100	1993	Detour Length (Miles)	3		Year Built and Rebuilt:	1917	1927	Historical Significance:	5		Open/Closed/Posted:	B		Number of Utilities:	0		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>611</td> </tr> <tr> <td>Curb to Curb:</td> <td>54</td> </tr> <tr> <td>Square feet of deck::</td> <td>32994</td> </tr> <tr> <td>Number of lanes on:</td> <td>4</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>54</td> </tr> </table>	Geometric Data:		Bridge Length:	611	Curb to Curb:	54	Square feet of deck::	32994	Number of lanes on:	4	Approach Roadway Width:	54
Age and Service Data:	Fed Func Class:	17																																			
Main/Appr Material Design:	0 00	2 04																																			
Average Daily Traffic Year:	33100	1993																																			
Detour Length (Miles)	3																																				
Year Built and Rebuilt:	1917	1927																																			
Historical Significance:	5																																				
Open/Closed/Posted:	B																																				
Number of Utilities:	0																																				
Geometric Data:																																					
Bridge Length:	611																																				
Curb to Curb:	54																																				
Square feet of deck::	32994																																				
Number of lanes on:	4																																				
Approach Roadway Width:	54																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Concrete</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2" style="height: 40px; vertical-align: top;"> Replace bridge approaches and replace movable bridge electrical mechanical system. </td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Concrete	New Sub Type:	Concrete	New Foundn Type:		Proposed work:		Replace bridge approaches and replace movable bridge electrical mechanical system.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>50700</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$4,200,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$300,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$14,347,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$1,453,000.00</td> </tr> <tr> <td>Approach:</td> <td>\$300,000.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	50700	Preliminary Engineering:	\$4,200,000.00	Right of Way:	\$300,000.00	Construction:	\$14,347,000.00	Other Projected Costs:	\$1,453,000.00	Approach:	\$300,000.00										
Agency Replacement Comments:																																					
New Super Type:	Concrete																																				
New Sub Type:	Concrete																																				
New Foundn Type:																																					
Proposed work:																																					
Replace bridge approaches and replace movable bridge electrical mechanical system.																																					
Agency Replacement Costs:																																					
New Square Foot:	50700																																				
Preliminary Engineering:	\$4,200,000.00																																				
Right of Way:	\$300,000.00																																				
Construction:	\$14,347,000.00																																				
Other Projected Costs:	\$1,453,000.00																																				
Approach:	\$300,000.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> <td>GOOD</td> <td>N/A</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	POOR	GOOD	N/A																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	FAIR	POOR	GOOD	N/A																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>11.5 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Grays Harbor County</td> </tr> <tr> <td>Bridge Name:</td> <td>COUGAR SMITH BRIDGE</td> </tr> <tr> <td>Intersecting:</td> <td>MIDDLE FORK SATSOP RIVER</td> </tr> <tr> <td>Strudture ID:</td> <td>08470700</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 10' 42" N</td> </tr> <tr> <td>Longitude:</td> <td>123° 30' 36" W</td> </tr> <tr> <td>Requester:</td> <td>Russ Esses @ (360) 249-4222</td> </tr> </table>	Sufficiency Rating:	11.5 SD	Bridge Owner Name:	Grays Harbor County	Bridge Name:	COUGAR SMITH BRIDGE	Intersecting:	MIDDLE FORK SATSOP RIVER	Strudture ID:	08470700	Federal Highway:	Off	Latitude:	47° 10' 42" N	Longitude:	123° 30' 36" W	Requester:	Russ Esses @ (360) 249-4222	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$1,936,200.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>8/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>3/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$1,936,200.00	Preliminary Engineering:	1/1/2002	Right of Way:	8/1/2002	Construction Start:	3/1/2003
Sufficiency Rating:	11.5 SD																												
Bridge Owner Name:	Grays Harbor County																												
Bridge Name:	COUGAR SMITH BRIDGE																												
Intersecting:	MIDDLE FORK SATSOP RIVER																												
Strudture ID:	08470700																												
Federal Highway:	Off																												
Latitude:	47° 10' 42" N																												
Longitude:	123° 30' 36" W																												
Requester:	Russ Esses @ (360) 249-4222																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$1,936,200.00																												
Preliminary Engineering:	1/1/2002																												
Right of Way:	8/1/2002																												
Construction Start:	3/1/2003																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Condition Codes:</td> <td>BridgeNo: 7370/0.1</td> </tr> <tr> <td>Deck:</td> <td>5</td> </tr> <tr> <td>Superstructure:</td> <td>5</td> </tr> <tr> <td>Substructure:</td> <td>3</td> </tr> <tr> <td>Scour:</td> <td>3</td> </tr> <tr> <td>Inventory Rating:</td> <td>27 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>39 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 7370/0.1	Deck:	5	Superstructure:	5	Substructure:	3	Scour:	3	Inventory Rating:	27 HS-20 (Tons)	Operating Rating:	39 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>3</td> </tr> <tr> <td>Deck Geometry:</td> <td>4</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>3</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>4</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	3	Deck Geometry:	4	Under Clearance:	9	Wate way:	8	Roadway Alignment:	3	Safe Load Capacity:	4
Condition Codes:	BridgeNo: 7370/0.1																												
Deck:	5																												
Superstructure:	5																												
Substructure:	3																												
Scour:	3																												
Inventory Rating:	27 HS-20 (Tons)																												
Operating Rating:	39 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	3																												
Deck Geometry:	4																												
Under Clearance:	9																												
Wate way:	8																												
Roadway Alignment:	3																												
Safe Load Capacity:	4																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Age and Service Data:</td> <td>Fed Func Class: 08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>3 10 7 02</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>274 1998</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>99</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1960 0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>R</td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> </tr> </table>	Age and Service Data:	Fed Func Class: 08	Main/Appr Material Design:	3 10 7 02	Average Daily Traffic Year:	274 1998	Detour Length (Miles)	99	Year Built and Rebuilt:	1960 0	Historical Significance:	4	Open/Closed/Posted:	R	Number of Utilities:	0	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>179</td> </tr> <tr> <td>Curb to Curb:</td> <td>21.5</td> </tr> <tr> <td>Square feet of deck::</td> <td>3848.5</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>25</td> </tr> </table>	Geometric Data:		Bridge Length:	179	Curb to Curb:	21.5	Square feet of deck::	3848.5	Number of lanes on:	2	Approach Roadway Width:	25
Age and Service Data:	Fed Func Class: 08																												
Main/Appr Material Design:	3 10 7 02																												
Average Daily Traffic Year:	274 1998																												
Detour Length (Miles)	99																												
Year Built and Rebuilt:	1960 0																												
Historical Significance:	4																												
Open/Closed/Posted:	R																												
Number of Utilities:	0																												
Geometric Data:																													
Bridge Length:	179																												
Curb to Curb:	21.5																												
Square feet of deck::	3848.5																												
Number of lanes on:	2																												
Approach Roadway Width:	25																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete Girders</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove and replace existing bridge with new concrete structure</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Girders	New Sub Type:	Concrete	New Foundn Type:		Proposed work:		Remove and replace existing bridge with new concrete structure		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>5600</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$162,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$30,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$1,080,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$486,000.00</td> </tr> <tr> <td>Approach:</td> <td>\$178,000.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	5600	Preliminary Engineering:	\$162,000.00	Right of Way:	\$30,000.00	Construction:	\$1,080,000.00	Other Projected Costs:	\$486,000.00	Approach:	\$178,000.00		
Agency Replacement Comments:																													
New Super Type:	Prestressed Concrete Girders																												
New Sub Type:	Concrete																												
New Foundn Type:																													
Proposed work:																													
Remove and replace existing bridge with new concrete structure																													
Agency Replacement Costs:																													
New Square Foot:	5600																												
Preliminary Engineering:	\$162,000.00																												
Right of Way:	\$30,000.00																												
Construction:	\$1,080,000.00																												
Other Projected Costs:	\$486,000.00																												
Approach:	\$178,000.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>FAIR</td> <td>FAIR</td> <td>GOOD</td> <td>GOOD</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	FAIR	FAIR	GOOD	GOOD	POOR													
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
FAIR	FAIR	GOOD	GOOD	POOR																									

2001 Spring Replacement Candidates

Sufficiency Rating: 19.47 SD Bridge Owner Name: Whitman County Bridge Name: WHITE ELEPHANT Intersecting: UNION FLAT CREEK Structure ID: 08326300 Federal Highway: On Latitude: 46° 51' 30" Longitude: 117° 51' 24" Requester: Derek Pohle @ 509-397-6206		Total Project Costs and Start Dates: Projected Replacement : \$842,980.00 Preliminary Engineering: 1/1/2002 Right of Way: 6/1/2002 Construction Start: 6/1/2003	
Condition Codes: BridgeNo: 600000818 Deck: 9 Superstructure: 5 Substructure: 6 Scour: 5 Inventory Rating: 0 HS-20 (Tons) Operating Rating: 20 HS-20 (Tons)		Adequacy Appraisal Codes: Structural: 2 Deck Geometry: 4 Under Clearance: 9 Wate way: 8 Roadway Alignment: 8 Safe Load Capacity: 5	
Age and Service Data: Fed Func Class: 07 Main/Appr Material Design: 1 11 0 00 Average Daily Traffic Year: 155 1977 Detour Length (Miles) 41 Year Built and Rebuilt: 1917 0 Historical Significance: 5 Open/Closed/Posted: A Number of Utilities: 0		Geometric Data: Bridge Length: 91 Curb to Curb: 20 Square feet of deck:: 1820 Number of lanes on: 2 Approach Roadway Width: 28	
Agency Replacement Comments: New Super Type: Prestressed concrete beams New Sub Type: Concrete Abutments New Foundn Type: Spread Footings Proposed work: Remove structure, place piling, abutments, wingwalls, girders, install guardrail and approaches.		Agency Replacement Costs: New Square Foot: 3840 Preliminary Engineering: \$64,800.00 Right of Way: \$1,000.00 Construction: \$432,000.00 Other Projected Costs: \$269,400.00 Approach: \$75,780.00	
Technical Committee Comment			
Load Capacity GOOD	Bridge Geometrics FAIR	Approach Geometrics POOR	Bridge Condition FAIR
			Hydraulics POOR

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>20.02 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Grant County</td> </tr> <tr> <td>Bridge Name:</td> <td>3 NW</td> </tr> <tr> <td>Intersecting:</td> <td>WEST CANAL</td> </tr> <tr> <td>Strudture ID:</td> <td>08156000</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 13' 6" N</td> </tr> <tr> <td>Longitude:</td> <td>119° 52' 36" W</td> </tr> <tr> <td>Requester:</td> <td>Bob Bersanti @ 509-754-6082</td> </tr> </table>	Sufficiency Rating:	20.02 SD	Bridge Owner Name:	Grant County	Bridge Name:	3 NW	Intersecting:	WEST CANAL	Strudture ID:	08156000	Federal Highway:	Off	Latitude:	47° 13' 6" N	Longitude:	119° 52' 36" W	Requester:	Bob Bersanti @ 509-754-6082	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$307,804.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>10/1/2002</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$307,804.00	Preliminary Engineering:	6/1/2002	Right of Way:		Construction Start:	10/1/2002								
Sufficiency Rating:	20.02 SD																																				
Bridge Owner Name:	Grant County																																				
Bridge Name:	3 NW																																				
Intersecting:	WEST CANAL																																				
Strudture ID:	08156000																																				
Federal Highway:	Off																																				
Latitude:	47° 13' 6" N																																				
Longitude:	119° 52' 36" W																																				
Requester:	Bob Bersanti @ 509-754-6082																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$307,804.00																																				
Preliminary Engineering:	6/1/2002																																				
Right of Way:																																					
Construction Start:	10/1/2002																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>390</td> </tr> <tr> <td>Deck:</td> <td>4</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>5</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>6</td> <td></td> </tr> <tr> <td>Scour:</td> <td>5</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>9</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>17</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	390	Deck:	4		Superstructure:	5		Substructure:	6		Scour:	5		Inventory Rating:	9	HS-20 (Tons)	Operating Rating:	17	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>2</td> </tr> <tr> <td>Deck Geometry:</td> <td>6</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>3</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>0</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	2	Deck Geometry:	6	Under Clearance:	9	Wate way:	8	Roadway Alignment:	3	Safe Load Capacity:	0	
Condition Codes:	BridgeNo:	390																																			
Deck:	4																																				
Superstructure:	5																																				
Substructure:	6																																				
Scour:	5																																				
Inventory Rating:	9	HS-20 (Tons)																																			
Operating Rating:	17	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	2																																				
Deck Geometry:	6																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	3																																				
Safe Load Capacity:	0																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>82</td> <td>1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>99</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1950</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	09	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	82	1996	Detour Length (Miles)	99		Year Built and Rebuilt:	1950	0	Historical Significance:	4		Open/Closed/Posted:	P		Number of Utilities:	0		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>91</td> </tr> <tr> <td>Curb to Curb:</td> <td>24.2</td> </tr> <tr> <td>Square feet of deck::</td> <td>2202.19995</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>28</td> </tr> </table>	Geometric Data:		Bridge Length:	91	Curb to Curb:	24.2	Square feet of deck::	2202.19995	Number of lanes on:	2	Approach Roadway Width:	28
Age and Service Data:	Fed Func Class:	09																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	82	1996																																			
Detour Length (Miles)	99																																				
Year Built and Rebuilt:	1950	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	0																																				
Geometric Data:																																					
Bridge Length:	91																																				
Curb to Curb:	24.2																																				
Square feet of deck::	2202.19995																																				
Number of lanes on:	2																																				
Approach Roadway Width:	28																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete Bulb-T girders</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutment walls</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Bulb-T girders	New Sub Type:	Concrete abutment walls	New Foundn Type:		Proposed work:		Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>2800</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$40,148.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$182,700.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$54,810.00</td> </tr> <tr> <td>Approach:</td> <td>\$30,146.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	2800	Preliminary Engineering:	\$40,148.00	Right of Way:	\$0.00	Construction:	\$182,700.00	Other Projected Costs:	\$54,810.00	Approach:	\$30,146.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed Concrete Bulb-T girders																																				
New Sub Type:	Concrete abutment walls																																				
New Foundn Type:																																					
Proposed work:																																					
Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction																																					
Agency Replacement Costs:																																					
New Square Foot:	2800																																				
Preliminary Engineering:	\$40,148.00																																				
Right of Way:	\$0.00																																				
Construction:	\$182,700.00																																				
Other Projected Costs:	\$54,810.00																																				
Approach:	\$30,146.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	GOOD	FAIR	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	FAIR	GOOD	FAIR	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>26.45 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Thurston County</td> </tr> <tr> <td>Bridge Name:</td> <td>OLD PACIFIC HWY BRIDGE</td> </tr> <tr> <td>Intersecting:</td> <td>SCATTER CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08259100</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>46° 51' 48" N</td> </tr> <tr> <td>Longitude:</td> <td>122° 50' 42" W</td> </tr> <tr> <td>Requester:</td> <td>Don Pogreba @ (360) 754-4580</td> </tr> </table>		Sufficiency Rating:	26.45 SD	Bridge Owner Name:	Thurston County	Bridge Name:	OLD PACIFIC HWY BRIDGE	Intersecting:	SCATTER CREEK	Strudture ID:	08259100	Federal Highway:	On	Latitude:	46° 51' 48" N	Longitude:	122° 50' 42" W	Requester:	Don Pogreba @ (360) 754-4580	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Total Project Costs and Start Dates:</th> </tr> <tr> <td>Projected Replacement :</td> <td>\$1,239,695.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>11/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td>3/1/2004</td> </tr> <tr> <td>Construction Start:</td> <td>7/1/2004</td> </tr> </table>		Total Project Costs and Start Dates:		Projected Replacement :	\$1,239,695.00	Preliminary Engineering:	11/1/2001	Right of Way:	3/1/2004	Construction Start:	7/1/2004							
Sufficiency Rating:	26.45 SD																																					
Bridge Owner Name:	Thurston County																																					
Bridge Name:	OLD PACIFIC HWY BRIDGE																																					
Intersecting:	SCATTER CREEK																																					
Strudture ID:	08259100																																					
Federal Highway:	On																																					
Latitude:	46° 51' 48" N																																					
Longitude:	122° 50' 42" W																																					
Requester:	Don Pogreba @ (360) 754-4580																																					
Total Project Costs and Start Dates:																																						
Projected Replacement :	\$1,239,695.00																																					
Preliminary Engineering:	11/1/2001																																					
Right of Way:	3/1/2004																																					
Construction Start:	7/1/2004																																					
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Condition Codes:</td> <td>BridgeNo:</td> <td>O-9</td> </tr> <tr> <td>Deck:</td> <td>5</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>5</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>4</td> <td></td> </tr> <tr> <td>Scour:</td> <td>5</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>24</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>54</td> <td>HS-20 (Tons)</td> </tr> </table>		Condition Codes:	BridgeNo:	O-9	Deck:	5		Superstructure:	5		Substructure:	4		Scour:	5		Inventory Rating:	24	HS-20 (Tons)	Operating Rating:	54	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Adequacy Appraisal Codes:</th> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>7</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>		Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	2	Under Clearance:	9	Wate way:	7	Roadway Alignment:	6	Safe Load Capacity:	5
Condition Codes:	BridgeNo:	O-9																																				
Deck:	5																																					
Superstructure:	5																																					
Substructure:	4																																					
Scour:	5																																					
Inventory Rating:	24	HS-20 (Tons)																																				
Operating Rating:	54	HS-20 (Tons)																																				
Adequacy Appraisal Codes:																																						
Structural:	4																																					
Deck Geometry:	2																																					
Under Clearance:	9																																					
Wate way:	7																																					
Roadway Alignment:	6																																					
Safe Load Capacity:	5																																					
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Age and Service Data:</th> </tr> <tr> <td>Fed Func Class:</td> <td>07</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>2 01 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>4199 1999</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>16</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1923 0</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>2</td> </tr> </table>		Age and Service Data:		Fed Func Class:	07	Main/Appr Material Design:	2 01 0 00	Average Daily Traffic Year:	4199 1999	Detour Length (Miles)	16	Year Built and Rebuilt:	1923 0	Historical Significance:	5	Open/Closed/Posted:	A	Number of Utilities:	2	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Geometric Data:</th> </tr> <tr> <td>Bridge Length:</td> <td>81</td> </tr> <tr> <td>Curb to Curb:</td> <td>24.1</td> </tr> <tr> <td>Square feet of deck::</td> <td>1952.09998</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>33</td> </tr> </table>		Geometric Data:		Bridge Length:	81	Curb to Curb:	24.1	Square feet of deck::	1952.09998	Number of lanes on:	2	Approach Roadway Width:	33					
Age and Service Data:																																						
Fed Func Class:	07																																					
Main/Appr Material Design:	2 01 0 00																																					
Average Daily Traffic Year:	4199 1999																																					
Detour Length (Miles)	16																																					
Year Built and Rebuilt:	1923 0																																					
Historical Significance:	5																																					
Open/Closed/Posted:	A																																					
Number of Utilities:	2																																					
Geometric Data:																																						
Bridge Length:	81																																					
Curb to Curb:	24.1																																					
Square feet of deck::	1952.09998																																					
Number of lanes on:	2																																					
Approach Roadway Width:	33																																					
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Agency Replacement Comments:</th> </tr> <tr> <td>New Super Type:</td> <td>Precast Stringer, slab deck</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete caps</td> </tr> <tr> <td>New Foundn Type:</td> <td>Pile Footing</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2" style="height: 40px; vertical-align: top;">Replace bridge and roadway approaches.</td> </tr> </table>		Agency Replacement Comments:		New Super Type:	Precast Stringer, slab deck	New Sub Type:	Concrete caps	New Foundn Type:	Pile Footing	Proposed work:		Replace bridge and roadway approaches.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Agency Replacement Costs:</th> </tr> <tr> <td>New Square Foot:</td> <td>4410</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$99,450.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$35,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$663,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$328,350.00</td> </tr> <tr> <td>Approach:</td> <td>\$113,895.00</td> </tr> </table>		Agency Replacement Costs:		New Square Foot:	4410	Preliminary Engineering:	\$99,450.00	Right of Way:	\$35,000.00	Construction:	\$663,000.00	Other Projected Costs:	\$328,350.00	Approach:	\$113,895.00									
Agency Replacement Comments:																																						
New Super Type:	Precast Stringer, slab deck																																					
New Sub Type:	Concrete caps																																					
New Foundn Type:	Pile Footing																																					
Proposed work:																																						
Replace bridge and roadway approaches.																																						
Agency Replacement Costs:																																						
New Square Foot:	4410																																					
Preliminary Engineering:	\$99,450.00																																					
Right of Way:	\$35,000.00																																					
Construction:	\$663,000.00																																					
Other Projected Costs:	\$328,350.00																																					
Approach:	\$113,895.00																																					
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="5" style="text-align: left;">Technical Committee Comment</th> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>FAIR</td> <td>GOOD</td> <td>FAIR</td> <td>GOOD</td> <td>POOR</td> </tr> </table>				Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	FAIR	GOOD	FAIR	GOOD	POOR																				
Technical Committee Comment																																						
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																		
FAIR	GOOD	FAIR	GOOD	POOR																																		

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Sufficiency Rating:</td> <td>35.39 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Pacific County</td> </tr> <tr> <td>Bridge Name:</td> <td>NO. NEMAH RV. BR.</td> </tr> <tr> <td>Intersecting:</td> <td>NORTH NEMAH RIVER</td> </tr> <tr> <td>Strudture ID:</td> <td>08171100</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>46° 31' 30" N</td> </tr> <tr> <td>Longitude:</td> <td>123° 52' 18" W</td> </tr> <tr> <td>Requester:</td> <td>Mike Collins @ (509) 875-9368</td> </tr> </table>	Sufficiency Rating:	35.39 SD	Bridge Owner Name:	Pacific County	Bridge Name:	NO. NEMAH RV. BR.	Intersecting:	NORTH NEMAH RIVER	Strudture ID:	08171100	Federal Highway:	Off	Latitude:	46° 31' 30" N	Longitude:	123° 52' 18" W	Requester:	Mike Collins @ (509) 875-9368	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$521,750.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>1/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$521,750.00	Preliminary Engineering:	1/1/2002	Right of Way:	1/1/2002	Construction Start:	6/1/2003								
Sufficiency Rating:	35.39 SD																																				
Bridge Owner Name:	Pacific County																																				
Bridge Name:	NO. NEMAH RV. BR.																																				
Intersecting:	NORTH NEMAH RIVER																																				
Strudture ID:	08171100																																				
Federal Highway:	Off																																				
Latitude:	46° 31' 30" N																																				
Longitude:	123° 52' 18" W																																				
Requester:	Mike Collins @ (509) 875-9368																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$521,750.00																																				
Preliminary Engineering:	1/1/2002																																				
Right of Way:	1/1/2002																																				
Construction Start:	6/1/2003																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Condition Codes:</td> <td>BridgeNo:</td> <td>940802</td> </tr> <tr> <td>Deck:</td> <td>4</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>4</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>4</td> <td></td> </tr> <tr> <td>Scour:</td> <td>T</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>24</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>34</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	940802	Deck:	4		Superstructure:	4		Substructure:	4		Scour:	T		Inventory Rating:	24	HS-20 (Tons)	Operating Rating:	34	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>4</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	4	Under Clearance:	9	Wate way:	8	Roadway Alignment:	8	Safe Load Capacity:	5	
Condition Codes:	BridgeNo:	940802																																			
Deck:	4																																				
Superstructure:	4																																				
Substructure:	4																																				
Scour:	T																																				
Inventory Rating:	24	HS-20 (Tons)																																			
Operating Rating:	34	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	4																																				
Deck Geometry:	4																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	8																																				
Safe Load Capacity:	5																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Age and Service Data:</td> <td>Fed Func Class:</td> <td>08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>426</td> <td>2000</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>99</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1952</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>B</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>2</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	08	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	426	2000	Detour Length (Miles)	99		Year Built and Rebuilt:	1952	0	Historical Significance:	4		Open/Closed/Posted:	B		Number of Utilities:	2		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>101</td> </tr> <tr> <td>Curb to Curb:</td> <td>23</td> </tr> <tr> <td>Square feet of deck::</td> <td>2323</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>24</td> </tr> </table>	Geometric Data:		Bridge Length:	101	Curb to Curb:	23	Square feet of deck::	2323	Number of lanes on:	2	Approach Roadway Width:	24
Age and Service Data:	Fed Func Class:	08																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	426	2000																																			
Detour Length (Miles)	99																																				
Year Built and Rebuilt:	1952	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	B																																				
Number of Utilities:	2																																				
Geometric Data:																																					
Bridge Length:	101																																				
Curb to Curb:	23																																				
Square feet of deck::	2323																																				
Number of lanes on:	2																																				
Approach Roadway Width:	24																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete Beams</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Caps</td> </tr> <tr> <td>New Foundn Type:</td> <td>Piling</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove and replace existing timber bridge with a new prestress concrete beam bridge.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Beams	New Sub Type:	Concrete Caps	New Foundn Type:	Piling	Proposed work:		Remove and replace existing timber bridge with a new prestress concrete beam bridge.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>2800</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$66,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$25,500.00</td> </tr> <tr> <td>Construction:</td> <td>\$221,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$165,450.00</td> </tr> <tr> <td>Approach:</td> <td>\$43,800.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	2800	Preliminary Engineering:	\$66,000.00	Right of Way:	\$25,500.00	Construction:	\$221,000.00	Other Projected Costs:	\$165,450.00	Approach:	\$43,800.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed Concrete Beams																																				
New Sub Type:	Concrete Caps																																				
New Foundn Type:	Piling																																				
Proposed work:																																					
Remove and replace existing timber bridge with a new prestress concrete beam bridge.																																					
Agency Replacement Costs:																																					
New Square Foot:	2800																																				
Preliminary Engineering:	\$66,000.00																																				
Right of Way:	\$25,500.00																																				
Construction:	\$221,000.00																																				
Other Projected Costs:	\$165,450.00																																				
Approach:	\$43,800.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td>Load Capacity</td> <td>Bridge Geometrics</td> <td>Approach Geometrics</td> <td>Bridge Condition</td> <td>Hydraulics</td> </tr> <tr> <td>FAIR</td> <td>FAIR</td> <td>POOR</td> <td>GOOD</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	FAIR	FAIR	POOR	GOOD	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
FAIR	FAIR	POOR	GOOD	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>35.85 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Columbia County</td> </tr> <tr> <td>Bridge Name:</td> <td>WINNETT</td> </tr> <tr> <td>Intersecting:</td> <td>WHISKY CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08268900</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>46° 14' 42"</td> </tr> <tr> <td>Longitude:</td> <td>118° 4' 42"</td> </tr> <tr> <td>Requester:</td> <td>Robert K. Yates @ (509) 382-2534</td> </tr> </table>	Sufficiency Rating:	35.85 SD	Bridge Owner Name:	Columbia County	Bridge Name:	WINNETT	Intersecting:	WHISKY CREEK	Strudture ID:	08268900	Federal Highway:	Off	Latitude:	46° 14' 42"	Longitude:	118° 4' 42"	Requester:	Robert K. Yates @ (509) 382-2534	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$222,338.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>7/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td>9/1/2001</td> </tr> <tr> <td>Construction Start:</td> <td>7/1/2002</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$222,338.00	Preliminary Engineering:	7/1/2001	Right of Way:	9/1/2001	Construction Start:	7/1/2002								
Sufficiency Rating:	35.85 SD																																				
Bridge Owner Name:	Columbia County																																				
Bridge Name:	WINNETT																																				
Intersecting:	WHISKY CREEK																																				
Strudture ID:	08268900																																				
Federal Highway:	Off																																				
Latitude:	46° 14' 42"																																				
Longitude:	118° 4' 42"																																				
Requester:	Robert K. Yates @ (509) 382-2534																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$222,338.00																																				
Preliminary Engineering:	7/1/2001																																				
Right of Way:	9/1/2001																																				
Construction Start:	7/1/2002																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Condition Codes:</td> <td>BridgeNo:</td> <td>69</td> </tr> <tr> <td>Deck:</td> <td>7</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>3</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>7</td> <td></td> </tr> <tr> <td>Scour:</td> <td>U</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>17</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>24</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	69	Deck:	7		Superstructure:	3		Substructure:	7		Scour:	U		Inventory Rating:	17	HS-20 (Tons)	Operating Rating:	24	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>3</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>5</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>3</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	3	Deck Geometry:	2	Under Clearance:	9	Wate way:	5	Roadway Alignment:	6	Safe Load Capacity:	3	
Condition Codes:	BridgeNo:	69																																			
Deck:	7																																				
Superstructure:	3																																				
Substructure:	7																																				
Scour:	U																																				
Inventory Rating:	17	HS-20 (Tons)																																			
Operating Rating:	24	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	3																																				
Deck Geometry:	2																																				
Under Clearance:	9																																				
Wate way:	5																																				
Roadway Alignment:	6																																				
Safe Load Capacity:	3																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>50</td> <td>1991</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>10</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1956</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	08	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	50	1991	Detour Length (Miles)	10		Year Built and Rebuilt:	1956	0	Historical Significance:	4		Open/Closed/Posted:	P		Number of Utilities:	1		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>32</td> </tr> <tr> <td>Curb to Curb:</td> <td>19</td> </tr> <tr> <td>Square feet of deck::</td> <td>608</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>20</td> </tr> </table>	Geometric Data:		Bridge Length:	32	Curb to Curb:	19	Square feet of deck::	608	Number of lanes on:	2	Approach Roadway Width:	20
Age and Service Data:	Fed Func Class:	08																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	50	1991																																			
Detour Length (Miles)	10																																				
Year Built and Rebuilt:	1956	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	1																																				
Geometric Data:																																					
Bridge Length:	32																																				
Curb to Curb:	19																																				
Square feet of deck::	608																																				
Number of lanes on:	2																																				
Approach Roadway Width:	20																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Spread Footings or Steel Piles</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2" style="height: 40px; vertical-align: top;">Minimal approach work and replacement of the small bridge.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete	New Sub Type:	Concrete Abutments	New Foundn Type:	Spread Footings or Steel Piles	Proposed work:		Minimal approach work and replacement of the small bridge.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>1540</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$17,625.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$117,500.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$65,875.00</td> </tr> <tr> <td>Approach:</td> <td>\$21,338.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	1540	Preliminary Engineering:	\$17,625.00	Right of Way:	\$0.00	Construction:	\$117,500.00	Other Projected Costs:	\$65,875.00	Approach:	\$21,338.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed Concrete																																				
New Sub Type:	Concrete Abutments																																				
New Foundn Type:	Spread Footings or Steel Piles																																				
Proposed work:																																					
Minimal approach work and replacement of the small bridge.																																					
Agency Replacement Costs:																																					
New Square Foot:	1540																																				
Preliminary Engineering:	\$17,625.00																																				
Right of Way:	\$0.00																																				
Construction:	\$117,500.00																																				
Other Projected Costs:	\$65,875.00																																				
Approach:	\$21,338.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>FAIR</td> <td>GOOD</td> <td>FAIR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	FAIR	GOOD	FAIR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	FAIR	FAIR	GOOD	FAIR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Sufficiency Rating:</td> <td>36.84 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Walla Walla County</td> </tr> <tr> <td>Bridge Name:</td> <td>HARVEY SHAW</td> </tr> <tr> <td>Intersecting:</td> <td>TOUCHET RIVER</td> </tr> <tr> <td>Strudture ID:</td> <td>08053700</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>46° 17' 6" Longitude: 118° 28' 48"</td> </tr> <tr> <td>Requester:</td> <td>David Eids @ (509) 527-3241</td> </tr> </table>	Sufficiency Rating:	36.84 SD	Bridge Owner Name:	Walla Walla County	Bridge Name:	HARVEY SHAW	Intersecting:	TOUCHET RIVER	Strudture ID:	08053700	Federal Highway:	On	Latitude:	46° 17' 6" Longitude: 118° 28' 48"	Requester:	David Eids @ (509) 527-3241	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$845,450.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>6/1/2003</td> </tr> <tr> <td>Construction Start:</td> <td>7/1/2004</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$845,450.00	Preliminary Engineering:	6/1/2002	Right of Way:	6/1/2003	Construction Start:	7/1/2004		
Sufficiency Rating:	36.84 SD																												
Bridge Owner Name:	Walla Walla County																												
Bridge Name:	HARVEY SHAW																												
Intersecting:	TOUCHET RIVER																												
Strudture ID:	08053700																												
Federal Highway:	On																												
Latitude:	46° 17' 6" Longitude: 118° 28' 48"																												
Requester:	David Eids @ (509) 527-3241																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$845,450.00																												
Preliminary Engineering:	6/1/2002																												
Right of Way:	6/1/2003																												
Construction Start:	7/1/2004																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Condition Codes:</td> <td>BridgeNo: 936500003</td> </tr> <tr> <td>Deck:</td> <td>6</td> </tr> <tr> <td>Superstructure:</td> <td>6</td> </tr> <tr> <td>Substructure:</td> <td>3</td> </tr> <tr> <td>Scour:</td> <td>3</td> </tr> <tr> <td>Inventory Rating:</td> <td>27 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>44 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 936500003	Deck:	6	Superstructure:	6	Substructure:	3	Scour:	3	Inventory Rating:	27 HS-20 (Tons)	Operating Rating:	44 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>3</td> </tr> <tr> <td>Deck Geometry:</td> <td>5</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>4</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	3	Deck Geometry:	5	Under Clearance:	9	Wate way:	8	Roadway Alignment:	4	Safe Load Capacity:	5
Condition Codes:	BridgeNo: 936500003																												
Deck:	6																												
Superstructure:	6																												
Substructure:	3																												
Scour:	3																												
Inventory Rating:	27 HS-20 (Tons)																												
Operating Rating:	44 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	3																												
Deck Geometry:	5																												
Under Clearance:	9																												
Wate way:	8																												
Roadway Alignment:	4																												
Safe Load Capacity:	5																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Age and Service Data:</td> <td>Fed Func Class: 07</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>1 04 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>480 1997</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>28</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1948 0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> </tr> </table>	Age and Service Data:	Fed Func Class: 07	Main/Appr Material Design:	1 04 0 00	Average Daily Traffic Year:	480 1997	Detour Length (Miles)	28	Year Built and Rebuilt:	1948 0	Historical Significance:	4	Open/Closed/Posted:	A	Number of Utilities:	1	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>100</td> </tr> <tr> <td>Curb to Curb:</td> <td>26</td> </tr> <tr> <td>Square feet of deck::</td> <td>2600</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>26</td> </tr> </table>	Geometric Data:		Bridge Length:	100	Curb to Curb:	26	Square feet of deck::	2600	Number of lanes on:	2	Approach Roadway Width:	26
Age and Service Data:	Fed Func Class: 07																												
Main/Appr Material Design:	1 04 0 00																												
Average Daily Traffic Year:	480 1997																												
Detour Length (Miles)	28																												
Year Built and Rebuilt:	1948 0																												
Historical Significance:	4																												
Open/Closed/Posted:	A																												
Number of Utilities:	1																												
Geometric Data:																													
Bridge Length:	100																												
Curb to Curb:	26																												
Square feet of deck::	2600																												
Number of lanes on:	2																												
Approach Roadway Width:	26																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Concrete Girders with CIP deck</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Spread Footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove an existing concrete multi-span bridge and install a single span concrete bridge. Install guard rail and concrete approach slabs. Reconstruct roadway.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Concrete Girders with CIP deck	New Sub Type:	Concrete abutments	New Foundn Type:	Spread Footings	Proposed work:		Remove an existing concrete multi-span bridge and install a single span concrete bridge. Install guard rail and concrete approach slabs. Reconstruct roadway.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>4800</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$64,500.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$6,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$430,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$263,500.00</td> </tr> <tr> <td>Approach:</td> <td>\$81,450.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	4800	Preliminary Engineering:	\$64,500.00	Right of Way:	\$6,000.00	Construction:	\$430,000.00	Other Projected Costs:	\$263,500.00	Approach:	\$81,450.00		
Agency Replacement Comments:																													
New Super Type:	Concrete Girders with CIP deck																												
New Sub Type:	Concrete abutments																												
New Foundn Type:	Spread Footings																												
Proposed work:																													
Remove an existing concrete multi-span bridge and install a single span concrete bridge. Install guard rail and concrete approach slabs. Reconstruct roadway.																													
Agency Replacement Costs:																													
New Square Foot:	4800																												
Preliminary Engineering:	\$64,500.00																												
Right of Way:	\$6,000.00																												
Construction:	\$430,000.00																												
Other Projected Costs:	\$263,500.00																												
Approach:	\$81,450.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td>Load Capacity</td> <td>Bridge Geometrics</td> <td>Approach Geometrics</td> <td>Bridge Condition</td> <td>Hydraulics</td> </tr> <tr> <td>FAIR</td> <td>FAIR</td> <td>FAIR</td> <td>GOOD</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	FAIR	FAIR	FAIR	GOOD	POOR													
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
FAIR	FAIR	FAIR	GOOD	POOR																									

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>37.23 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Grant County</td> </tr> <tr> <td>Bridge Name:</td> <td>A NW</td> </tr> <tr> <td>Intersecting:</td> <td>W 22 IRRIGATION LATERAL</td> </tr> <tr> <td>Strudture ID:</td> <td>08129400</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 14' 30"</td> </tr> <tr> <td>Longitude:</td> <td>119° 30' 36"</td> </tr> <tr> <td>Requester:</td> <td>Bob Bersanti @ (509) 754-6082</td> </tr> </table>	Sufficiency Rating:	37.23 SD	Bridge Owner Name:	Grant County	Bridge Name:	A NW	Intersecting:	W 22 IRRIGATION LATERAL	Strudture ID:	08129400	Federal Highway:	Off	Latitude:	47° 14' 30"	Longitude:	119° 30' 36"	Requester:	Bob Bersanti @ (509) 754-6082	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$246,243.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>10/1/2001</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$246,243.00	Preliminary Engineering:	6/1/2001	Right of Way:		Construction Start:	10/1/2001								
Sufficiency Rating:	37.23 SD																																				
Bridge Owner Name:	Grant County																																				
Bridge Name:	A NW																																				
Intersecting:	W 22 IRRIGATION LATERAL																																				
Strudture ID:	08129400																																				
Federal Highway:	Off																																				
Latitude:	47° 14' 30"																																				
Longitude:	119° 30' 36"																																				
Requester:	Bob Bersanti @ (509) 754-6082																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$246,243.00																																				
Preliminary Engineering:	6/1/2001																																				
Right of Way:																																					
Construction Start:	10/1/2001																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>377</td> </tr> <tr> <td>Deck:</td> <td>6</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>5</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>7</td> <td></td> </tr> <tr> <td>Scour:</td> <td>5</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>10</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>20</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	377	Deck:	6		Superstructure:	5		Substructure:	7		Scour:	5		Inventory Rating:	10	HS-20 (Tons)	Operating Rating:	20	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>2</td> </tr> <tr> <td>Deck Geometry:</td> <td>5</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>2</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	2	Deck Geometry:	5	Under Clearance:	9	Wate way:	8	Roadway Alignment:	6	Safe Load Capacity:	2	
Condition Codes:	BridgeNo:	377																																			
Deck:	6																																				
Superstructure:	5																																				
Substructure:	7																																				
Scour:	5																																				
Inventory Rating:	10	HS-20 (Tons)																																			
Operating Rating:	20	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	2																																				
Deck Geometry:	5																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	6																																				
Safe Load Capacity:	2																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>166</td> <td>1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>15</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1954</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	09	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	166	1996	Detour Length (Miles)	15		Year Built and Rebuilt:	1954	0	Historical Significance:	4		Open/Closed/Posted:	P		Number of Utilities:	1		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>68</td> </tr> <tr> <td>Curb to Curb:</td> <td>24</td> </tr> <tr> <td>Square feet of deck::</td> <td>1632</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>30</td> </tr> </table>	Geometric Data:		Bridge Length:	68	Curb to Curb:	24	Square feet of deck::	1632	Number of lanes on:	2	Approach Roadway Width:	30
Age and Service Data:	Fed Func Class:	09																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	166	1996																																			
Detour Length (Miles)	15																																				
Year Built and Rebuilt:	1954	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	1																																				
Geometric Data:																																					
Bridge Length:	68																																				
Curb to Curb:	24																																				
Square feet of deck::	1632																																				
Number of lanes on:	2																																				
Approach Roadway Width:	30																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed concrete Bulb-T girders</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutment walls</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed concrete Bulb-T girders	New Sub Type:	Concrete abutment walls	New Foundn Type:		Proposed work:		Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>3360</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$32,119.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$146,160.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$43,848.00</td> </tr> <tr> <td>Approach:</td> <td>\$24,116.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	3360	Preliminary Engineering:	\$32,119.00	Right of Way:	\$0.00	Construction:	\$146,160.00	Other Projected Costs:	\$43,848.00	Approach:	\$24,116.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed concrete Bulb-T girders																																				
New Sub Type:	Concrete abutment walls																																				
New Foundn Type:																																					
Proposed work:																																					
Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction																																					
Agency Replacement Costs:																																					
New Square Foot:	3360																																				
Preliminary Engineering:	\$32,119.00																																				
Right of Way:	\$0.00																																				
Construction:	\$146,160.00																																				
Other Projected Costs:	\$43,848.00																																				
Approach:	\$24,116.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>FAIR</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	FAIR	FAIR	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	FAIR	FAIR	FAIR	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Sufficiency Rating:</td> <td>38.35 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Whitman County</td> </tr> <tr> <td>Bridge Name:</td> <td>JUDSON</td> </tr> <tr> <td>Intersecting:</td> <td>MISSOURI FLAT CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08303300</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>46° 46' 18" N</td> </tr> <tr> <td>Longitude:</td> <td>117° 8' 6" W</td> </tr> <tr> <td>Requester:</td> <td>Derek Pohle, P.E. @ 509-397-6206</td> </tr> </table>	Sufficiency Rating:	38.35 SD	Bridge Owner Name:	Whitman County	Bridge Name:	JUDSON	Intersecting:	MISSOURI FLAT CREEK	Strudture ID:	08303300	Federal Highway:	Off	Latitude:	46° 46' 18" N	Longitude:	117° 8' 6" W	Requester:	Derek Pohle, P.E. @ 509-397-6206	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$492,988.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>6/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$492,988.00	Preliminary Engineering:	1/1/2002	Right of Way:	6/1/2002	Construction Start:	6/1/2003
Sufficiency Rating:	38.35 SD																												
Bridge Owner Name:	Whitman County																												
Bridge Name:	JUDSON																												
Intersecting:	MISSOURI FLAT CREEK																												
Strudture ID:	08303300																												
Federal Highway:	Off																												
Latitude:	46° 46' 18" N																												
Longitude:	117° 8' 6" W																												
Requester:	Derek Pohle, P.E. @ 509-397-6206																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$492,988.00																												
Preliminary Engineering:	1/1/2002																												
Right of Way:	6/1/2002																												
Construction Start:	6/1/2003																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Condition Codes:</td> <td>BridgeNo: 551500190</td> </tr> <tr> <td>Deck:</td> <td>6</td> </tr> <tr> <td>Superstructure:</td> <td>6</td> </tr> <tr> <td>Substructure:</td> <td>4</td> </tr> <tr> <td>Scour:</td> <td>3</td> </tr> <tr> <td>Inventory Rating:</td> <td>18 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>26 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 551500190	Deck:	6	Superstructure:	6	Substructure:	4	Scour:	3	Inventory Rating:	18 HS-20 (Tons)	Operating Rating:	26 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>4</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>7</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>4</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	4	Under Clearance:	9	Wate way:	7	Roadway Alignment:	8	Safe Load Capacity:	4
Condition Codes:	BridgeNo: 551500190																												
Deck:	6																												
Superstructure:	6																												
Substructure:	4																												
Scour:	3																												
Inventory Rating:	18 HS-20 (Tons)																												
Operating Rating:	26 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	4																												
Deck Geometry:	4																												
Under Clearance:	9																												
Wate way:	7																												
Roadway Alignment:	8																												
Safe Load Capacity:	4																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Age and Service Data:</td> <td>Fed Func Class: 08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>108 1994</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>15</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1900 1951</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> </tr> </table>	Age and Service Data:	Fed Func Class: 08	Main/Appr Material Design:	7 02 0 00	Average Daily Traffic Year:	108 1994	Detour Length (Miles)	15	Year Built and Rebuilt:	1900 1951	Historical Significance:	5	Open/Closed/Posted:	P	Number of Utilities:	1	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>32</td> </tr> <tr> <td>Curb to Curb:</td> <td>23.5</td> </tr> <tr> <td>Square feet of deck::</td> <td>752</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>28</td> </tr> </table>	Geometric Data:		Bridge Length:	32	Curb to Curb:	23.5	Square feet of deck::	752	Number of lanes on:	2	Approach Roadway Width:	28
Age and Service Data:	Fed Func Class: 08																												
Main/Appr Material Design:	7 02 0 00																												
Average Daily Traffic Year:	108 1994																												
Detour Length (Miles)	15																												
Year Built and Rebuilt:	1900 1951																												
Historical Significance:	5																												
Open/Closed/Posted:	P																												
Number of Utilities:	1																												
Geometric Data:																													
Bridge Length:	32																												
Curb to Curb:	23.5																												
Square feet of deck::	752																												
Number of lanes on:	2																												
Approach Roadway Width:	28																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>PCB</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Piling or Spread Footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove structure, place piling, abutments, wingwalls, girders, install guardrail and approaches.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	PCB	New Sub Type:	Concrete Abutments	New Foundn Type:	Piling or Spread Footings	Proposed work:		Remove structure, place piling, abutments, wingwalls, girders, install guardrail and approaches.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>1920</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$38,880.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$1,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$259,200.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$146,640.00</td> </tr> <tr> <td>Approach:</td> <td>\$47,268.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	1920	Preliminary Engineering:	\$38,880.00	Right of Way:	\$1,000.00	Construction:	\$259,200.00	Other Projected Costs:	\$146,640.00	Approach:	\$47,268.00		
Agency Replacement Comments:																													
New Super Type:	PCB																												
New Sub Type:	Concrete Abutments																												
New Foundn Type:	Piling or Spread Footings																												
Proposed work:																													
Remove structure, place piling, abutments, wingwalls, girders, install guardrail and approaches.																													
Agency Replacement Costs:																													
New Square Foot:	1920																												
Preliminary Engineering:	\$38,880.00																												
Right of Way:	\$1,000.00																												
Construction:	\$259,200.00																												
Other Projected Costs:	\$146,640.00																												
Approach:	\$47,268.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td>Load Capacity</td> <td>Bridge Geometrics</td> <td>Approach Geometrics</td> <td>Bridge Condition</td> <td>Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> <td>GOOD</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	POOR	GOOD	POOR													
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
GOOD	FAIR	POOR	GOOD	POOR																									

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>39.14 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Grant County</td> </tr> <tr> <td>Bridge Name:</td> <td>7 NW</td> </tr> <tr> <td>Intersecting:</td> <td>WEST CANAL</td> </tr> <tr> <td>Strudture ID:</td> <td>08340200</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 11' 24" N</td> </tr> <tr> <td>Longitude:</td> <td>119° 52' 30" W</td> </tr> <tr> <td>Requester:</td> <td>Bob Bersanti @ 509-754-6082</td> </tr> </table>	Sufficiency Rating:	39.14 SD	Bridge Owner Name:	Grant County	Bridge Name:	7 NW	Intersecting:	WEST CANAL	Strudture ID:	08340200	Federal Highway:	Off	Latitude:	47° 11' 24" N	Longitude:	119° 52' 30" W	Requester:	Bob Bersanti @ 509-754-6082	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$369,365.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>10/1/2001</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$369,365.00	Preliminary Engineering:	6/1/2001	Right of Way:		Construction Start:	10/1/2001								
Sufficiency Rating:	39.14 SD																																				
Bridge Owner Name:	Grant County																																				
Bridge Name:	7 NW																																				
Intersecting:	WEST CANAL																																				
Strudture ID:	08340200																																				
Federal Highway:	Off																																				
Latitude:	47° 11' 24" N																																				
Longitude:	119° 52' 30" W																																				
Requester:	Bob Bersanti @ 509-754-6082																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$369,365.00																																				
Preliminary Engineering:	6/1/2001																																				
Right of Way:																																					
Construction Start:	10/1/2001																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Condition Codes:</td> <td>BridgeNo:</td> <td>388</td> </tr> <tr> <td>Deck:</td> <td>5</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>5</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>5</td> <td></td> </tr> <tr> <td>Scour:</td> <td>8</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>11</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>20</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	388	Deck:	5		Superstructure:	5		Substructure:	5		Scour:	8		Inventory Rating:	11	HS-20 (Tons)	Operating Rating:	20	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>2</td> </tr> <tr> <td>Deck Geometry:</td> <td>5</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>7</td> </tr> <tr> <td>Roadway Alignment:</td> <td>7</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>2</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	2	Deck Geometry:	5	Under Clearance:	9	Wate way:	7	Roadway Alignment:	7	Safe Load Capacity:	2	
Condition Codes:	BridgeNo:	388																																			
Deck:	5																																				
Superstructure:	5																																				
Substructure:	5																																				
Scour:	8																																				
Inventory Rating:	11	HS-20 (Tons)																																			
Operating Rating:	20	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	2																																				
Deck Geometry:	5																																				
Under Clearance:	9																																				
Wate way:	7																																				
Roadway Alignment:	7																																				
Safe Load Capacity:	2																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Age and Service Data:</td> <td>Fed Func Class:</td> <td>08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>389</td> <td>1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>4</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1949</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	08	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	389	1996	Detour Length (Miles)	4		Year Built and Rebuilt:	1949	0	Historical Significance:	4		Open/Closed/Posted:	P		Number of Utilities:	1		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>111</td> </tr> <tr> <td>Curb to Curb:</td> <td>24</td> </tr> <tr> <td>Square feet of deck::</td> <td>2664</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>24</td> </tr> </table>	Geometric Data:		Bridge Length:	111	Curb to Curb:	24	Square feet of deck::	2664	Number of lanes on:	2	Approach Roadway Width:	24
Age and Service Data:	Fed Func Class:	08																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	389	1996																																			
Detour Length (Miles)	4																																				
Year Built and Rebuilt:	1949	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	1																																				
Geometric Data:																																					
Bridge Length:	111																																				
Curb to Curb:	24																																				
Square feet of deck::	2664																																				
Number of lanes on:	2																																				
Approach Roadway Width:	24																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed concrete Bulb-T Girders</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutment walls</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Prestressed Concrete girders, concrete abutment walls, guardrail, and approach reconstruction</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed concrete Bulb-T Girders	New Sub Type:	Concrete abutment walls	New Foundn Type:		Proposed work:		Prestressed Concrete girders, concrete abutment walls, guardrail, and approach reconstruction		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>3360</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$48,178.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$219,240.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$65,772.00</td> </tr> <tr> <td>Approach:</td> <td>\$36,175.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	3360	Preliminary Engineering:	\$48,178.00	Right of Way:	\$0.00	Construction:	\$219,240.00	Other Projected Costs:	\$65,772.00	Approach:	\$36,175.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed concrete Bulb-T Girders																																				
New Sub Type:	Concrete abutment walls																																				
New Foundn Type:																																					
Proposed work:																																					
Prestressed Concrete girders, concrete abutment walls, guardrail, and approach reconstruction																																					
Agency Replacement Costs:																																					
New Square Foot:	3360																																				
Preliminary Engineering:	\$48,178.00																																				
Right of Way:	\$0.00																																				
Construction:	\$219,240.00																																				
Other Projected Costs:	\$65,772.00																																				
Approach:	\$36,175.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Technical Committee Comment</td> <td>Funded at Fall 2000 BRAC meeting.</td> </tr> <tr> <td>Load Capacity</td> <td>Bridge Geometrics</td> <td>Approach Geometrics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment		Funded at Fall 2000 BRAC meeting.	Load Capacity	Bridge Geometrics	Approach Geometrics	GOOD	FAIR	POOR																											
Technical Committee Comment		Funded at Fall 2000 BRAC meeting.																																			
Load Capacity	Bridge Geometrics	Approach Geometrics																																			
GOOD	FAIR	POOR																																			

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>39.45 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Grant County</td> </tr> <tr> <td>Bridge Name:</td> <td>M NW</td> </tr> <tr> <td>Intersecting:</td> <td>LAT. BLK 73</td> </tr> <tr> <td>Strudture ID:</td> <td>08143200</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 14' 42" N</td> </tr> <tr> <td>Longitude:</td> <td>119° 46' 0" W</td> </tr> <tr> <td>Requester:</td> <td>Bob Bersanti @ 509-754-6082</td> </tr> </table>	Sufficiency Rating:	39.45 SD	Bridge Owner Name:	Grant County	Bridge Name:	M NW	Intersecting:	LAT. BLK 73	Strudture ID:	08143200	Federal Highway:	Off	Latitude:	47° 14' 42" N	Longitude:	119° 46' 0" W	Requester:	Bob Bersanti @ 509-754-6082	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$369,365.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>10/1/2001</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$369,365.00	Preliminary Engineering:	6/1/2001	Right of Way:		Construction Start:	10/1/2001								
Sufficiency Rating:	39.45 SD																																				
Bridge Owner Name:	Grant County																																				
Bridge Name:	M NW																																				
Intersecting:	LAT. BLK 73																																				
Strudture ID:	08143200																																				
Federal Highway:	Off																																				
Latitude:	47° 14' 42" N																																				
Longitude:	119° 46' 0" W																																				
Requester:	Bob Bersanti @ 509-754-6082																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$369,365.00																																				
Preliminary Engineering:	6/1/2001																																				
Right of Way:																																					
Construction Start:	10/1/2001																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>386</td> </tr> <tr> <td>Deck:</td> <td>6</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>4</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>5</td> <td></td> </tr> <tr> <td>Scour:</td> <td>5</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>12</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>23</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	386	Deck:	6		Superstructure:	4		Substructure:	5		Scour:	5		Inventory Rating:	12	HS-20 (Tons)	Operating Rating:	23	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>2</td> </tr> <tr> <td>Deck Geometry:</td> <td>5</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>2</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	2	Deck Geometry:	5	Under Clearance:	9	Wate way:	8	Roadway Alignment:	6	Safe Load Capacity:	2	
Condition Codes:	BridgeNo:	386																																			
Deck:	6																																				
Superstructure:	4																																				
Substructure:	5																																				
Scour:	5																																				
Inventory Rating:	12	HS-20 (Tons)																																			
Operating Rating:	23	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	2																																				
Deck Geometry:	5																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	6																																				
Safe Load Capacity:	2																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>695</td> <td>1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>3</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1950</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	08	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	695	1996	Detour Length (Miles)	3		Year Built and Rebuilt:	1950	0	Historical Significance:	4		Open/Closed/Posted:	P		Number of Utilities:	1		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>107</td> </tr> <tr> <td>Curb to Curb:</td> <td>29.3</td> </tr> <tr> <td>Square feet of deck::</td> <td>3135.09985</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>29</td> </tr> </table>	Geometric Data:		Bridge Length:	107	Curb to Curb:	29.3	Square feet of deck::	3135.09985	Number of lanes on:	2	Approach Roadway Width:	29
Age and Service Data:	Fed Func Class:	08																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	695	1996																																			
Detour Length (Miles)	3																																				
Year Built and Rebuilt:	1950	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	1																																				
Geometric Data:																																					
Bridge Length:	107																																				
Curb to Curb:	29.3																																				
Square feet of deck::	3135.09985																																				
Number of lanes on:	2																																				
Approach Roadway Width:	29																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed concrete Bulb-T girders</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutment walls</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Prestressed concrete girders, concrete abutment walls, guardrails, and approach reconstruction</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed concrete Bulb-T girders	New Sub Type:	Concrete abutment walls	New Foundn Type:		Proposed work:		Prestressed concrete girders, concrete abutment walls, guardrails, and approach reconstruction		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>3360</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$48,178.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$219,240.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$65,772.00</td> </tr> <tr> <td>Approach:</td> <td>\$36,175.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	3360	Preliminary Engineering:	\$48,178.00	Right of Way:	\$0.00	Construction:	\$219,240.00	Other Projected Costs:	\$65,772.00	Approach:	\$36,175.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed concrete Bulb-T girders																																				
New Sub Type:	Concrete abutment walls																																				
New Foundn Type:																																					
Proposed work:																																					
Prestressed concrete girders, concrete abutment walls, guardrails, and approach reconstruction																																					
Agency Replacement Costs:																																					
New Square Foot:	3360																																				
Preliminary Engineering:	\$48,178.00																																				
Right of Way:	\$0.00																																				
Construction:	\$219,240.00																																				
Other Projected Costs:	\$65,772.00																																				
Approach:	\$36,175.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Technical Committee Comment</td> <td>Geometrics reflect a poor candidate due to building a narrower bridge.</td> </tr> <tr> <td>Load Capacity</td> <td>Bridge Geometrics</td> <td>Approach Geometrics</td> </tr> <tr> <td>GOOD</td> <td>POOR</td> <td>FAIR</td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td>Bridge Condition</td> <td colspan="2">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td colspan="2">POOR</td> </tr> <tr> <td></td> <td colspan="2"></td> </tr> </table>		Technical Committee Comment		Geometrics reflect a poor candidate due to building a narrower bridge.	Load Capacity	Bridge Geometrics	Approach Geometrics	GOOD	POOR	FAIR				Bridge Condition	Hydraulics		GOOD	POOR																			
Technical Committee Comment		Geometrics reflect a poor candidate due to building a narrower bridge.																																			
Load Capacity	Bridge Geometrics	Approach Geometrics																																			
GOOD	POOR	FAIR																																			
Bridge Condition	Hydraulics																																				
GOOD	POOR																																				

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>39.92 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Walla Walla County</td> </tr> <tr> <td>Bridge Name:</td> <td>ALDRIDGE</td> </tr> <tr> <td>Intersecting:</td> <td>DRY CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08578700</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>46° 7' 24"</td> </tr> <tr> <td>Longitude:</td> <td>118° 12' 54"</td> </tr> <tr> <td>Requester:</td> <td>David Eids @ (509) 527-3241</td> </tr> </table>	Sufficiency Rating:	39.92 SD	Bridge Owner Name:	Walla Walla County	Bridge Name:	ALDRIDGE	Intersecting:	DRY CREEK	Strudture ID:	08578700	Federal Highway:	Off	Latitude:	46° 7' 24"	Longitude:	118° 12' 54"	Requester:	David Eids @ (509) 527-3241	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$478,550.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>6/1/2003</td> </tr> <tr> <td>Construction Start:</td> <td>7/1/2004</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$478,550.00	Preliminary Engineering:	6/1/2002	Right of Way:	6/1/2003	Construction Start:	7/1/2004
Sufficiency Rating:	39.92 SD																												
Bridge Owner Name:	Walla Walla County																												
Bridge Name:	ALDRIDGE																												
Intersecting:	DRY CREEK																												
Strudture ID:	08578700																												
Federal Highway:	Off																												
Latitude:	46° 7' 24"																												
Longitude:	118° 12' 54"																												
Requester:	David Eids @ (509) 527-3241																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$478,550.00																												
Preliminary Engineering:	6/1/2002																												
Right of Way:	6/1/2003																												
Construction Start:	7/1/2004																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Condition Codes:</td> <td>BridgeNo: 661600011</td> </tr> <tr> <td>Deck:</td> <td>6</td> </tr> <tr> <td>Superstructure:</td> <td>7</td> </tr> <tr> <td>Substructure:</td> <td>3</td> </tr> <tr> <td>Scour:</td> <td>2</td> </tr> <tr> <td>Inventory Rating:</td> <td>19 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>28 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 661600011	Deck:	6	Superstructure:	7	Substructure:	3	Scour:	2	Inventory Rating:	19 HS-20 (Tons)	Operating Rating:	28 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>3</td> </tr> <tr> <td>Deck Geometry:</td> <td>5</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>6</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>0</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	3	Deck Geometry:	5	Under Clearance:	9	Wate way:	6	Roadway Alignment:	6	Safe Load Capacity:	0
Condition Codes:	BridgeNo: 661600011																												
Deck:	6																												
Superstructure:	7																												
Substructure:	3																												
Scour:	2																												
Inventory Rating:	19 HS-20 (Tons)																												
Operating Rating:	28 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	3																												
Deck Geometry:	5																												
Under Clearance:	9																												
Wate way:	6																												
Roadway Alignment:	6																												
Safe Load Capacity:	0																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Age and Service Data:</td> <td>Fed Func Class: 08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>48 1994</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>6</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1955 1990</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> </tr> </table>	Age and Service Data:	Fed Func Class: 08	Main/Appr Material Design:	7 02 0 00	Average Daily Traffic Year:	48 1994	Detour Length (Miles)	6	Year Built and Rebuilt:	1955 1990	Historical Significance:	5	Open/Closed/Posted:	P	Number of Utilities:	0	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>24</td> </tr> <tr> <td>Curb to Curb:</td> <td>20.9</td> </tr> <tr> <td>Square feet of deck::</td> <td>501.599976</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>22</td> </tr> </table>	Geometric Data:		Bridge Length:	24	Curb to Curb:	20.9	Square feet of deck::	501.599976	Number of lanes on:	2	Approach Roadway Width:	22
Age and Service Data:	Fed Func Class: 08																												
Main/Appr Material Design:	7 02 0 00																												
Average Daily Traffic Year:	48 1994																												
Detour Length (Miles)	6																												
Year Built and Rebuilt:	1955 1990																												
Historical Significance:	5																												
Open/Closed/Posted:	P																												
Number of Utilities:	0																												
Geometric Data:																													
Bridge Length:	24																												
Curb to Curb:	20.9																												
Square feet of deck::	501.599976																												
Number of lanes on:	2																												
Approach Roadway Width:	22																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Deck Bulb-t Girders</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Abutment</td> </tr> <tr> <td>New Foundn Type:</td> <td>Spread Footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove existing timber bridge and replace with a concrete bridge. Install guardrail, concrete approach slabs, and reconstruct roadway.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Deck Bulb-t Girders	New Sub Type:	Concrete Abutment	New Foundn Type:	Spread Footings	Proposed work:		Remove existing timber bridge and replace with a concrete bridge. Install guardrail, concrete approach slabs, and reconstruct roadway.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>2240</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$40,500.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$2,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$270,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$121,500.00</td> </tr> <tr> <td>Approach:</td> <td>\$44,550.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	2240	Preliminary Engineering:	\$40,500.00	Right of Way:	\$2,000.00	Construction:	\$270,000.00	Other Projected Costs:	\$121,500.00	Approach:	\$44,550.00		
Agency Replacement Comments:																													
New Super Type:	Deck Bulb-t Girders																												
New Sub Type:	Concrete Abutment																												
New Foundn Type:	Spread Footings																												
Proposed work:																													
Remove existing timber bridge and replace with a concrete bridge. Install guardrail, concrete approach slabs, and reconstruct roadway.																													
Agency Replacement Costs:																													
New Square Foot:	2240																												
Preliminary Engineering:	\$40,500.00																												
Right of Way:	\$2,000.00																												
Construction:	\$270,000.00																												
Other Projected Costs:	\$121,500.00																												
Approach:	\$44,550.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>FAIR</td> <td>GOOD</td> <td>FAIR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	FAIR	GOOD	FAIR													
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
GOOD	FAIR	FAIR	GOOD	FAIR																									

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>43.14 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Franklin County</td> </tr> <tr> <td>Bridge Name:</td> <td>IRONWOOD ROAD</td> </tr> <tr> <td>Intersecting:</td> <td>POTHOLES CANAL</td> </tr> <tr> <td>Strudture ID:</td> <td>08193000</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>46° 31' 12" N</td> </tr> <tr> <td>Longitude:</td> <td>119° 10' 0" W</td> </tr> <tr> <td>Requester:</td> <td>Matt Mahoney @ (509) 545-3514</td> </tr> </table>	Sufficiency Rating:	43.14 SD	Bridge Owner Name:	Franklin County	Bridge Name:	IRONWOOD ROAD	Intersecting:	POTHOLES CANAL	Strudture ID:	08193000	Federal Highway:	Off	Latitude:	46° 31' 12" N	Longitude:	119° 10' 0" W	Requester:	Matt Mahoney @ (509) 545-3514	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$500,201.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>11/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>10/1/2002</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$500,201.00	Preliminary Engineering:	11/1/2001	Right of Way:		Construction Start:	10/1/2002
Sufficiency Rating:	43.14 SD																												
Bridge Owner Name:	Franklin County																												
Bridge Name:	IRONWOOD ROAD																												
Intersecting:	POTHOLES CANAL																												
Strudture ID:	08193000																												
Federal Highway:	Off																												
Latitude:	46° 31' 12" N																												
Longitude:	119° 10' 0" W																												
Requester:	Matt Mahoney @ (509) 545-3514																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$500,201.00																												
Preliminary Engineering:	11/1/2001																												
Right of Way:																													
Construction Start:	10/1/2002																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Condition Codes:</td> <td>BridgeNo: 636-5.54</td> </tr> <tr> <td>Deck:</td> <td>6</td> </tr> <tr> <td>Superstructure:</td> <td>3</td> </tr> <tr> <td>Substructure:</td> <td>7</td> </tr> <tr> <td>Scour:</td> <td>8</td> </tr> <tr> <td>Inventory Rating:</td> <td>29 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>42 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 636-5.54	Deck:	6	Superstructure:	3	Substructure:	7	Scour:	8	Inventory Rating:	29 HS-20 (Tons)	Operating Rating:	42 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>3</td> </tr> <tr> <td>Deck Geometry:</td> <td>5</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>5</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	3	Deck Geometry:	5	Under Clearance:	9	Wate way:	8	Roadway Alignment:	5	Safe Load Capacity:	5
Condition Codes:	BridgeNo: 636-5.54																												
Deck:	6																												
Superstructure:	3																												
Substructure:	7																												
Scour:	8																												
Inventory Rating:	29 HS-20 (Tons)																												
Operating Rating:	42 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	3																												
Deck Geometry:	5																												
Under Clearance:	9																												
Wate way:	8																												
Roadway Alignment:	5																												
Safe Load Capacity:	5																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Age and Service Data:</td> <td>Fed Func Class: 09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>206 1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>10</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1958 0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> </tr> </table>	Age and Service Data:	Fed Func Class: 09	Main/Appr Material Design:	7 02 0 00	Average Daily Traffic Year:	206 1996	Detour Length (Miles)	10	Year Built and Rebuilt:	1958 0	Historical Significance:	4	Open/Closed/Posted:	A	Number of Utilities:	0	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>100</td> </tr> <tr> <td>Curb to Curb:</td> <td>24</td> </tr> <tr> <td>Square feet of deck::</td> <td>2400</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>26</td> </tr> </table>	Geometric Data:		Bridge Length:	100	Curb to Curb:	24	Square feet of deck::	2400	Number of lanes on:	2	Approach Roadway Width:	26
Age and Service Data:	Fed Func Class: 09																												
Main/Appr Material Design:	7 02 0 00																												
Average Daily Traffic Year:	206 1996																												
Detour Length (Miles)	10																												
Year Built and Rebuilt:	1958 0																												
Historical Significance:	4																												
Open/Closed/Posted:	A																												
Number of Utilities:	0																												
Geometric Data:																													
Bridge Length:	100																												
Curb to Curb:	24																												
Square feet of deck::	2400																												
Number of lanes on:	2																												
Approach Roadway Width:	26																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete Girder</td> </tr> <tr> <td>New Sub Type:</td> <td></td> </tr> <tr> <td>New Foundn Type:</td> <td>Dry crossing w/spread footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2" style="height: 40px;"></td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Girder	New Sub Type:		New Foundn Type:	Dry crossing w/spread footings	Proposed work:				<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>3080</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$42,510.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$283,400.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$127,530.00</td> </tr> <tr> <td>Approach:</td> <td>\$46,761.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	3080	Preliminary Engineering:	\$42,510.00	Right of Way:	\$0.00	Construction:	\$283,400.00	Other Projected Costs:	\$127,530.00	Approach:	\$46,761.00		
Agency Replacement Comments:																													
New Super Type:	Prestressed Concrete Girder																												
New Sub Type:																													
New Foundn Type:	Dry crossing w/spread footings																												
Proposed work:																													
Agency Replacement Costs:																													
New Square Foot:	3080																												
Preliminary Engineering:	\$42,510.00																												
Right of Way:	\$0.00																												
Construction:	\$283,400.00																												
Other Projected Costs:	\$127,530.00																												
Approach:	\$46,761.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>FAIR</td> <td>FAIR</td> <td>FAIR</td> <td>GOOD</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	FAIR	FAIR	FAIR	GOOD	POOR													
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
FAIR	FAIR	FAIR	GOOD	POOR																									

2001 Spring Replacement Candidates

Sufficiency Rating: 44 SD Bridge Owner Name: Columbia County Bridge Name: TRUMP - NORTH TOUCHET Intersecting: NORTH TOUCHET RIVER Strudture ID: 08119500 Federal Highway: Off Latitude: 46° 16' 18" Longitude: 117° 53' 24" Requester: Robert Yates @ (509) 382-2534		Total Project Costs and Start Dates: Projected Replacement : \$343,375.00 Preliminary Engineering: 7/1/2001 Right of Way: 9/1/2002 Construction Start: 7/1/2003											
Condition Codes: BridgeNo: 51 Deck: 6 Superstructure: 7 Substructure: 4 Scour: 2 Inventory Rating: 27 HS-20 (Tons) Operating Rating: 38 HS-20 (Tons)		Adequacy Appraisal Codes: Structural: 4 Deck Geometry: 5 Under Clearance: 9 Wate way: 5 Roadway Alignment: 6 Safe Load Capacity: 5											
Age and Service Data: Fed Func Class: 08 Main/Appr Material Design: 3 02 0 00 Average Daily Traffic Year: 200 1991 Detour Length (Miles) 99 Year Built and Rebuilt: 1969 0 Historical Significance: 4 Open/Closed/Posted: A Number of Utilities: 2		Geometric Data: Bridge Length: 52 Curb to Curb: 24.2 Square feet of deck:: 1258.40002 Number of lanes on: 2 Approach Roadway Width: 24											
Agency Replacement Comments: New Super Type: Prestressed Precast Girders New Sub Type: CIP concrete Piles New Foundn Type: H-piles or CIP Conc. Columns Proposed work: Remove existing structure and build a longer structure that will allow for skew, a wider channel, and place new substructure elements away form channel cross section.		Agency Replacement Costs: New Square Foot: 2560 Preliminary Engineering: \$26,250.00 Right of Way: \$0.00 Construction: \$175,000.00 Other Projected Costs: \$108,750.00 Approach: \$33,375.00											
Technical Committee Comment													
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>FAIR</td> <td>FAIR</td> <td>FAIR</td> <td>GOOD</td> <td>FAIR</td> </tr> </table>				Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	FAIR	FAIR	FAIR	GOOD	FAIR
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics									
FAIR	FAIR	FAIR	GOOD	FAIR									

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>44.45 FO</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Stevens County</td> </tr> <tr> <td>Bridge Name:</td> <td>HEDLUND</td> </tr> <tr> <td>Intersecting:</td> <td>KETTLE RIVER</td> </tr> <tr> <td>Strudture ID:</td> <td>08386500</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>48° 40' 24"</td> </tr> <tr> <td>Longitude:</td> <td>118° 6' 54"</td> </tr> <tr> <td>Requester:</td> <td>Jim Whitbread @ (509) 684-4548</td> </tr> </table>	Sufficiency Rating:	44.45 FO	Bridge Owner Name:	Stevens County	Bridge Name:	HEDLUND	Intersecting:	KETTLE RIVER	Strudture ID:	08386500	Federal Highway:	On	Latitude:	48° 40' 24"	Longitude:	118° 6' 54"	Requester:	Jim Whitbread @ (509) 684-4548	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$3,015,500.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td>5/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>5/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$3,015,500.00	Preliminary Engineering:	1/1/2001	Right of Way:	5/1/2002	Construction Start:	5/1/2003								
Sufficiency Rating:	44.45 FO																																				
Bridge Owner Name:	Stevens County																																				
Bridge Name:	HEDLUND																																				
Intersecting:	KETTLE RIVER																																				
Strudture ID:	08386500																																				
Federal Highway:	On																																				
Latitude:	48° 40' 24"																																				
Longitude:	118° 6' 54"																																				
Requester:	Jim Whitbread @ (509) 684-4548																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$3,015,500.00																																				
Preliminary Engineering:	1/1/2001																																				
Right of Way:	5/1/2002																																				
Construction Start:	5/1/2003																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Condition Codes:</td> <td>BridgeNo:</td> <td>226</td> </tr> <tr> <td>Deck:</td> <td>6</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>7</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>7</td> <td></td> </tr> <tr> <td>Scour:</td> <td>8</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>17</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>28</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	226	Deck:	6		Superstructure:	7		Substructure:	7		Scour:	8		Inventory Rating:	17	HS-20 (Tons)	Operating Rating:	28	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>1</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	2	Under Clearance:	9	Wate way:	8	Roadway Alignment:	8	Safe Load Capacity:	1	
Condition Codes:	BridgeNo:	226																																			
Deck:	6																																				
Superstructure:	7																																				
Substructure:	7																																				
Scour:	8																																				
Inventory Rating:	17	HS-20 (Tons)																																			
Operating Rating:	28	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	4																																				
Deck Geometry:	2																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	8																																				
Safe Load Capacity:	1																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Age and Service Data:</td> <td>Fed Func Class:</td> <td>07</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>3 10</td> <td>4 02</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>515</td> <td>2000</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>18</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1942</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	07	Main/Appr Material Design:	3 10	4 02	Average Daily Traffic Year:	515	2000	Detour Length (Miles)	18		Year Built and Rebuilt:	1942	0	Historical Significance:	4		Open/Closed/Posted:	P		Number of Utilities:	1		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>322</td> </tr> <tr> <td>Curb to Curb:</td> <td>18</td> </tr> <tr> <td>Square feet of deck::</td> <td>5796</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>22</td> </tr> </table>	Geometric Data:		Bridge Length:	322	Curb to Curb:	18	Square feet of deck::	5796	Number of lanes on:	2	Approach Roadway Width:	22
Age and Service Data:	Fed Func Class:	07																																			
Main/Appr Material Design:	3 10	4 02																																			
Average Daily Traffic Year:	515	2000																																			
Detour Length (Miles)	18																																				
Year Built and Rebuilt:	1942	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	1																																				
Geometric Data:																																					
Bridge Length:	322																																				
Curb to Curb:	18																																				
Square feet of deck::	5796																																				
Number of lanes on:	2																																				
Approach Roadway Width:	22																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete Beams, CIP Deck</td> </tr> <tr> <td>New Sub Type:</td> <td>Reinforced Concrete</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove and replace existing steel truss bridge.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Beams, CIP Deck	New Sub Type:	Reinforced Concrete	New Foundn Type:		Proposed work:		Remove and replace existing steel truss bridge.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>9100</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$170,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$100,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$1,700,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$765,000.00</td> </tr> <tr> <td>Approach:</td> <td>\$280,500.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	9100	Preliminary Engineering:	\$170,000.00	Right of Way:	\$100,000.00	Construction:	\$1,700,000.00	Other Projected Costs:	\$765,000.00	Approach:	\$280,500.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed Concrete Beams, CIP Deck																																				
New Sub Type:	Reinforced Concrete																																				
New Foundn Type:																																					
Proposed work:																																					
Remove and replace existing steel truss bridge.																																					
Agency Replacement Costs:																																					
New Square Foot:	9100																																				
Preliminary Engineering:	\$170,000.00																																				
Right of Way:	\$100,000.00																																				
Construction:	\$1,700,000.00																																				
Other Projected Costs:	\$765,000.00																																				
Approach:	\$280,500.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Technical Committee Comment</td> <td>Bridge is signed for one lane traffic</td> </tr> <tr> <td>Load Capacity</td> <td>Bridge Geometrics</td> <td>Approach Geometrics</td> </tr> <tr> <td>GOOD</td> <td>GOOD</td> <td>POOR</td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td>Bridge Condition</td> <td colspan="2">Hydraulics</td> </tr> <tr> <td>FAIR</td> <td colspan="2">POOR</td> </tr> <tr> <td></td> <td colspan="2"></td> </tr> </table>		Technical Committee Comment		Bridge is signed for one lane traffic	Load Capacity	Bridge Geometrics	Approach Geometrics	GOOD	GOOD	POOR				Bridge Condition	Hydraulics		FAIR	POOR																			
Technical Committee Comment		Bridge is signed for one lane traffic																																			
Load Capacity	Bridge Geometrics	Approach Geometrics																																			
GOOD	GOOD	POOR																																			
Bridge Condition	Hydraulics																																				
FAIR	POOR																																				

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>45.18 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Whatcom County</td> </tr> <tr> <td>Bridge Name:</td> <td>HUTCHINSON CR.</td> </tr> <tr> <td>Intersecting:</td> <td>HUTCHINSON CR</td> </tr> <tr> <td>Strudture ID:</td> <td>07984600</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>48° 43' 48" N</td> </tr> <tr> <td>Longitude:</td> <td>122° 7' 54" W</td> </tr> <tr> <td>Requester:</td> <td>Steve Dillon @ (360) 676-6730</td> </tr> </table>	Sufficiency Rating:	45.18 SD	Bridge Owner Name:	Whatcom County	Bridge Name:	HUTCHINSON CR.	Intersecting:	HUTCHINSON CR	Strudture ID:	07984600	Federal Highway:	Off	Latitude:	48° 43' 48" N	Longitude:	122° 7' 54" W	Requester:	Steve Dillon @ (360) 676-6730	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$533,955.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>9/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$533,955.00	Preliminary Engineering:	1/1/2002	Right of Way:	9/1/2002	Construction Start:	6/1/2003								
Sufficiency Rating:	45.18 SD																																				
Bridge Owner Name:	Whatcom County																																				
Bridge Name:	HUTCHINSON CR.																																				
Intersecting:	HUTCHINSON CR																																				
Strudture ID:	07984600																																				
Federal Highway:	Off																																				
Latitude:	48° 43' 48" N																																				
Longitude:	122° 7' 54" W																																				
Requester:	Steve Dillon @ (360) 676-6730																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$533,955.00																																				
Preliminary Engineering:	1/1/2002																																				
Right of Way:	9/1/2002																																				
Construction Start:	6/1/2003																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>157</td> </tr> <tr> <td>Deck:</td> <td>7</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>7</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>4</td> <td></td> </tr> <tr> <td>Scour:</td> <td>U</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>17</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>28</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	157	Deck:	7		Superstructure:	7		Substructure:	4		Scour:	U		Inventory Rating:	17	HS-20 (Tons)	Operating Rating:	28	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>4</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>7</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	4	Under Clearance:	9	Wate way:	7	Roadway Alignment:	8	Safe Load Capacity:	5	
Condition Codes:	BridgeNo:	157																																			
Deck:	7																																				
Superstructure:	7																																				
Substructure:	4																																				
Scour:	U																																				
Inventory Rating:	17	HS-20 (Tons)																																			
Operating Rating:	28	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	4																																				
Deck Geometry:	4																																				
Under Clearance:	9																																				
Wate way:	7																																				
Roadway Alignment:	8																																				
Safe Load Capacity:	5																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>1 22</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>750</td> <td>1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>21</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1953</td> <td>1969</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	08	Main/Appr Material Design:	1 22	0 00	Average Daily Traffic Year:	750	1996	Detour Length (Miles)	21		Year Built and Rebuilt:	1953	1969	Historical Significance:	4		Open/Closed/Posted:	A		Number of Utilities:	0		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>50</td> </tr> <tr> <td>Curb to Curb:</td> <td>24</td> </tr> <tr> <td>Square feet of deck::</td> <td>1200</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>27</td> </tr> </table>	Geometric Data:		Bridge Length:	50	Curb to Curb:	24	Square feet of deck::	1200	Number of lanes on:	2	Approach Roadway Width:	27
Age and Service Data:	Fed Func Class:	08																																			
Main/Appr Material Design:	1 22	0 00																																			
Average Daily Traffic Year:	750	1996																																			
Detour Length (Miles)	21																																				
Year Built and Rebuilt:	1953	1969																																			
Historical Significance:	4																																				
Open/Closed/Posted:	A																																				
Number of Utilities:	0																																				
Geometric Data:																																					
Bridge Length:	50																																				
Curb to Curb:	24																																				
Square feet of deck::	1200																																				
Number of lanes on:	2																																				
Approach Roadway Width:	27																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed deck bulb tee girders</td> </tr> <tr> <td>New Sub Type:</td> <td>CIP Piers</td> </tr> <tr> <td>New Foundn Type:</td> <td>Spread Footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Construct a new deck bulb tee girder bridge, approach roadway drainage work, detention and erosion control work.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed deck bulb tee girders	New Sub Type:	CIP Piers	New Foundn Type:	Spread Footings	Proposed work:		Construct a new deck bulb tee girder bridge, approach roadway drainage work, detention and erosion control work.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>2520</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$47,550.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$5,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$317,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$111,950.00</td> </tr> <tr> <td>Approach:</td> <td>\$52,455.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	2520	Preliminary Engineering:	\$47,550.00	Right of Way:	\$5,000.00	Construction:	\$317,000.00	Other Projected Costs:	\$111,950.00	Approach:	\$52,455.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed deck bulb tee girders																																				
New Sub Type:	CIP Piers																																				
New Foundn Type:	Spread Footings																																				
Proposed work:																																					
Construct a new deck bulb tee girder bridge, approach roadway drainage work, detention and erosion control work.																																					
Agency Replacement Costs:																																					
New Square Foot:	2520																																				
Preliminary Engineering:	\$47,550.00																																				
Right of Way:	\$5,000.00																																				
Construction:	\$317,000.00																																				
Other Projected Costs:	\$111,950.00																																				
Approach:	\$52,455.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	POOR	FAIR	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	FAIR	POOR	FAIR	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>46.19 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Grant County</td> </tr> <tr> <td>Bridge Name:</td> <td>E SE</td> </tr> <tr> <td>Intersecting:</td> <td>IRRIGATION LATERAL</td> </tr> <tr> <td>Strudture ID:</td> <td>08172800</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>46° 13' 12"</td> </tr> <tr> <td>Longitude:</td> <td>119° 23' 18"</td> </tr> <tr> <td>Requester:</td> <td>Bob Bersanti @ 509-754-6082</td> </tr> </table>	Sufficiency Rating:	46.19 SD	Bridge Owner Name:	Grant County	Bridge Name:	E SE	Intersecting:	IRRIGATION LATERAL	Strudture ID:	08172800	Federal Highway:	Off	Latitude:	46° 13' 12"	Longitude:	119° 23' 18"	Requester:	Bob Bersanti @ 509-754-6082	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$114,327.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>10/1/2002</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$114,327.00	Preliminary Engineering:	6/1/2002	Right of Way:		Construction Start:	10/1/2002								
Sufficiency Rating:	46.19 SD																																				
Bridge Owner Name:	Grant County																																				
Bridge Name:	E SE																																				
Intersecting:	IRRIGATION LATERAL																																				
Strudture ID:	08172800																																				
Federal Highway:	Off																																				
Latitude:	46° 13' 12"																																				
Longitude:	119° 23' 18"																																				
Requester:	Bob Bersanti @ 509-754-6082																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$114,327.00																																				
Preliminary Engineering:	6/1/2002																																				
Right of Way:																																					
Construction Start:	10/1/2002																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>313</td> </tr> <tr> <td>Deck:</td> <td>6</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>4</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>7</td> <td></td> </tr> <tr> <td>Scour:</td> <td>8</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>15</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>25</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	313	Deck:	6		Superstructure:	4		Substructure:	7		Scour:	8		Inventory Rating:	15	HS-20 (Tons)	Operating Rating:	25	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>6</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>3</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	6	Under Clearance:	9	Wate way:	8	Roadway Alignment:	6	Safe Load Capacity:	3	
Condition Codes:	BridgeNo:	313																																			
Deck:	6																																				
Superstructure:	4																																				
Substructure:	7																																				
Scour:	8																																				
Inventory Rating:	15	HS-20 (Tons)																																			
Operating Rating:	25	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	4																																				
Deck Geometry:	6																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	6																																				
Safe Load Capacity:	3																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>53</td> <td>1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>6</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1959</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	09	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	53	1996	Detour Length (Miles)	6		Year Built and Rebuilt:	1959	0	Historical Significance:	4		Open/Closed/Posted:	P		Number of Utilities:	0		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>31</td> </tr> <tr> <td>Curb to Curb:</td> <td>24.2</td> </tr> <tr> <td>Square feet of deck::</td> <td>750.200012</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>24</td> </tr> </table>	Geometric Data:		Bridge Length:	31	Curb to Curb:	24.2	Square feet of deck::	750.200012	Number of lanes on:	2	Approach Roadway Width:	24
Age and Service Data:	Fed Func Class:	09																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	53	1996																																			
Detour Length (Miles)	6																																				
Year Built and Rebuilt:	1959	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	0																																				
Geometric Data:																																					
Bridge Length:	31																																				
Curb to Curb:	24.2																																				
Square feet of deck::	750.200012																																				
Number of lanes on:	2																																				
Approach Roadway Width:	24																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed concrete girders</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutment walls</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed concrete girders	New Sub Type:	Concrete abutment walls	New Foundn Type:		Proposed work:		Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>1040</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$14,912.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$67,860.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$20,358.00</td> </tr> <tr> <td>Approach:</td> <td>\$11,197.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	1040	Preliminary Engineering:	\$14,912.00	Right of Way:	\$0.00	Construction:	\$67,860.00	Other Projected Costs:	\$20,358.00	Approach:	\$11,197.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed concrete girders																																				
New Sub Type:	Concrete abutment walls																																				
New Foundn Type:																																					
Proposed work:																																					
Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction																																					
Agency Replacement Costs:																																					
New Square Foot:	1040																																				
Preliminary Engineering:	\$14,912.00																																				
Right of Way:	\$0.00																																				
Construction:	\$67,860.00																																				
Other Projected Costs:	\$20,358.00																																				
Approach:	\$11,197.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>FAIR</td> <td>GOOD</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	FAIR	GOOD	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	FAIR	FAIR	GOOD	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>46.9 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Whitman County</td> </tr> <tr> <td>Bridge Name:</td> <td>FARBAND</td> </tr> <tr> <td>Intersecting:</td> <td>PARADISE CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>07963900</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>46° 43' 48"</td> </tr> <tr> <td>Longitude:</td> <td>117° 5' 12"</td> </tr> <tr> <td>Requester:</td> <td>Derek Pohle @ (509) 397-6206</td> </tr> </table>	Sufficiency Rating:	46.9 SD	Bridge Owner Name:	Whitman County	Bridge Name:	FARBAND	Intersecting:	PARADISE CREEK	Strudture ID:	07963900	Federal Highway:	Off	Latitude:	46° 43' 48"	Longitude:	117° 5' 12"	Requester:	Derek Pohle @ (509) 397-6206	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$667,360.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>6/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$667,360.00	Preliminary Engineering:	1/1/2002	Right of Way:	6/1/2002	Construction Start:	6/1/2003		
Sufficiency Rating:	46.9 SD																														
Bridge Owner Name:	Whitman County																														
Bridge Name:	FARBAND																														
Intersecting:	PARADISE CREEK																														
Strudture ID:	07963900																														
Federal Highway:	Off																														
Latitude:	46° 43' 48"																														
Longitude:	117° 5' 12"																														
Requester:	Derek Pohle @ (509) 397-6206																														
Total Project Costs and Start Dates:																															
Projected Replacement :	\$667,360.00																														
Preliminary Engineering:	1/1/2002																														
Right of Way:	6/1/2002																														
Construction Start:	6/1/2003																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo: 908000007</td> </tr> <tr> <td>Deck:</td> <td>4</td> </tr> <tr> <td>Superstructure:</td> <td>4</td> </tr> <tr> <td>Substructure:</td> <td>5</td> </tr> <tr> <td>Scour:</td> <td>5</td> </tr> <tr> <td>Inventory Rating:</td> <td>37 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>51 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 908000007	Deck:	4	Superstructure:	4	Substructure:	5	Scour:	5	Inventory Rating:	37 HS-20 (Tons)	Operating Rating:	51 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>3</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>4</td> </tr> <tr> <td>Roadway Alignment:</td> <td>3</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	3	Under Clearance:	9	Wate way:	4	Roadway Alignment:	3	Safe Load Capacity:	5		
Condition Codes:	BridgeNo: 908000007																														
Deck:	4																														
Superstructure:	4																														
Substructure:	5																														
Scour:	5																														
Inventory Rating:	37 HS-20 (Tons)																														
Operating Rating:	51 HS-20 (Tons)																														
Adequacy Appraisal Codes:																															
Structural:	4																														
Deck Geometry:	3																														
Under Clearance:	9																														
Wate way:	4																														
Roadway Alignment:	3																														
Safe Load Capacity:	5																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class: 08</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>60 1994</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>8</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1934 1959</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> </tr> </table>	Age and Service Data:	Fed Func Class: 08	Main/Appr Material Design:	7 02 0 00	Average Daily Traffic Year:	60 1994	Detour Length (Miles)	8	Year Built and Rebuilt:	1934 1959	Historical Significance:	5	Open/Closed/Posted:	A	Number of Utilities:	1	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>50</td> </tr> <tr> <td>Curb to Curb:</td> <td>11</td> </tr> <tr> <td>Square feet of deck::</td> <td>550</td> </tr> <tr> <td>Number of lanes on:</td> <td>1</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>20</td> </tr> </table>	Geometric Data:		Bridge Length:	50	Curb to Curb:	11	Square feet of deck::	550	Number of lanes on:	1	Approach Roadway Width:	20		
Age and Service Data:	Fed Func Class: 08																														
Main/Appr Material Design:	7 02 0 00																														
Average Daily Traffic Year:	60 1994																														
Detour Length (Miles)	8																														
Year Built and Rebuilt:	1934 1959																														
Historical Significance:	5																														
Open/Closed/Posted:	A																														
Number of Utilities:	1																														
Geometric Data:																															
Bridge Length:	50																														
Curb to Curb:	11																														
Square feet of deck::	550																														
Number of lanes on:	1																														
Approach Roadway Width:	20																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed concrete beams</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete</td> </tr> <tr> <td>New Foundn Type:</td> <td>Piling or Spread Footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove structure, place piling, abutments, wingwalls, girders, install guardrail, and approached.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed concrete beams	New Sub Type:	Concrete	New Foundn Type:	Piling or Spread Footings	Proposed work:		Remove structure, place piling, abutments, wingwalls, girders, install guardrail, and approached.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>2400</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$48,600.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$1,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$324,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$235,800.00</td> </tr> <tr> <td>Approach:</td> <td>\$57,960.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	2400	Preliminary Engineering:	\$48,600.00	Right of Way:	\$1,000.00	Construction:	\$324,000.00	Other Projected Costs:	\$235,800.00	Approach:	\$57,960.00				
Agency Replacement Comments:																															
New Super Type:	Prestressed concrete beams																														
New Sub Type:	Concrete																														
New Foundn Type:	Piling or Spread Footings																														
Proposed work:																															
Remove structure, place piling, abutments, wingwalls, girders, install guardrail, and approached.																															
Agency Replacement Costs:																															
New Square Foot:	2400																														
Preliminary Engineering:	\$48,600.00																														
Right of Way:	\$1,000.00																														
Construction:	\$324,000.00																														
Other Projected Costs:	\$235,800.00																														
Approach:	\$57,960.00																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="10">Technical Committee Comment</td> </tr> <tr> <td colspan="2">Load Capacity</td> <td colspan="2">Bridge Geometrics</td> <td colspan="2">Approach Geometrics</td> <td colspan="2">Bridge Condition</td> <td colspan="2">Hydraulics</td> </tr> <tr> <td>POOR</td> <td></td> <td>FAIR</td> <td></td> <td>GOOD</td> <td></td> <td>GOOD</td> <td></td> <td>POOR</td> <td></td> </tr> </table>		Technical Committee Comment										Load Capacity		Bridge Geometrics		Approach Geometrics		Bridge Condition		Hydraulics		POOR		FAIR		GOOD		GOOD		POOR	
Technical Committee Comment																															
Load Capacity		Bridge Geometrics		Approach Geometrics		Bridge Condition		Hydraulics																							
POOR		FAIR		GOOD		GOOD		POOR																							

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>47.12 FO</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Grant County</td> </tr> <tr> <td>Bridge Name:</td> <td>F NE</td> </tr> <tr> <td>Intersecting:</td> <td>MAIN CANAL</td> </tr> <tr> <td>Strudture ID:</td> <td>08053200</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 25' 54"</td> </tr> <tr> <td>Longitude:</td> <td>119° 21' 42"</td> </tr> <tr> <td>Requester:</td> <td>Bob Bersanti @ 509-754-6082</td> </tr> </table>	Sufficiency Rating:	47.12 FO	Bridge Owner Name:	Grant County	Bridge Name:	F NE	Intersecting:	MAIN CANAL	Strudture ID:	08053200	Federal Highway:	Off	Latitude:	47° 25' 54"	Longitude:	119° 21' 42"	Requester:	Bob Bersanti @ 509-754-6082	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$408,393.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>10/1/2002</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$408,393.00	Preliminary Engineering:	6/1/2002	Right of Way:		Construction Start:	10/1/2002								
Sufficiency Rating:	47.12 FO																																				
Bridge Owner Name:	Grant County																																				
Bridge Name:	F NE																																				
Intersecting:	MAIN CANAL																																				
Strudture ID:	08053200																																				
Federal Highway:	Off																																				
Latitude:	47° 25' 54"																																				
Longitude:	119° 21' 42"																																				
Requester:	Bob Bersanti @ 509-754-6082																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$408,393.00																																				
Preliminary Engineering:	6/1/2002																																				
Right of Way:																																					
Construction Start:	10/1/2002																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>118</td> </tr> <tr> <td>Deck:</td> <td>5</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>6</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>7</td> <td></td> </tr> <tr> <td>Scour:</td> <td>8</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>13</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>13</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	118	Deck:	5		Superstructure:	6		Substructure:	7		Scour:	8		Inventory Rating:	13	HS-20 (Tons)	Operating Rating:	13	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>3</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	2	Under Clearance:	9	Wate way:	8	Roadway Alignment:	6	Safe Load Capacity:	3	
Condition Codes:	BridgeNo:	118																																			
Deck:	5																																				
Superstructure:	6																																				
Substructure:	7																																				
Scour:	8																																				
Inventory Rating:	13	HS-20 (Tons)																																			
Operating Rating:	13	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	4																																				
Deck Geometry:	2																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	6																																				
Safe Load Capacity:	3																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>3 10</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>99</td> <td>1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>12</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1948</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	09	Main/Appr Material Design:	3 10	0 00	Average Daily Traffic Year:	99	1996	Detour Length (Miles)	12		Year Built and Rebuilt:	1948	0	Historical Significance:	4		Open/Closed/Posted:	P		Number of Utilities:	0		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>144</td> </tr> <tr> <td>Curb to Curb:</td> <td>10.6</td> </tr> <tr> <td>Square feet of deck::</td> <td>1526.40002</td> </tr> <tr> <td>Number of lanes on:</td> <td>1</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>20</td> </tr> </table>	Geometric Data:		Bridge Length:	144	Curb to Curb:	10.6	Square feet of deck::	1526.40002	Number of lanes on:	1	Approach Roadway Width:	20
Age and Service Data:	Fed Func Class:	09																																			
Main/Appr Material Design:	3 10	0 00																																			
Average Daily Traffic Year:	99	1996																																			
Detour Length (Miles)	12																																				
Year Built and Rebuilt:	1948	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	P																																				
Number of Utilities:	0																																				
Geometric Data:																																					
Bridge Length:	144																																				
Curb to Curb:	10.6																																				
Square feet of deck::	1526.40002																																				
Number of lanes on:	1																																				
Approach Roadway Width:	20																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed concrete girders</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutment walls</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed concrete girders	New Sub Type:	Concrete abutment walls	New Foundn Type:		Proposed work:		Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>3720</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$53,340.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$242,730.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$72,819.00</td> </tr> <tr> <td>Approach:</td> <td>\$40,050.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	3720	Preliminary Engineering:	\$53,340.00	Right of Way:	\$0.00	Construction:	\$242,730.00	Other Projected Costs:	\$72,819.00	Approach:	\$40,050.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed concrete girders																																				
New Sub Type:	Concrete abutment walls																																				
New Foundn Type:																																					
Proposed work:																																					
Prestressed concrete girders, concrete abutment walls, guardrail, and approach reconstruction																																					
Agency Replacement Costs:																																					
New Square Foot:	3720																																				
Preliminary Engineering:	\$53,340.00																																				
Right of Way:	\$0.00																																				
Construction:	\$242,730.00																																				
Other Projected Costs:	\$72,819.00																																				
Approach:	\$40,050.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>GOOD</td> <td>FAIR</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	GOOD	FAIR	FAIR	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	GOOD	FAIR	FAIR	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>47.16 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Whitman County</td> </tr> <tr> <td>Bridge Name:</td> <td>WASSUM</td> </tr> <tr> <td>Intersecting:</td> <td>IMBLER CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08359700</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 6' 18"</td> </tr> <tr> <td>Longitude:</td> <td>117° 53' 30"</td> </tr> <tr> <td>Requester:</td> <td>Derek Pohle @ (509) 397-6206</td> </tr> </table>	Sufficiency Rating:	47.16 SD	Bridge Owner Name:	Whitman County	Bridge Name:	WASSUM	Intersecting:	IMBLER CREEK	Strudture ID:	08359700	Federal Highway:	Off	Latitude:	47° 6' 18"	Longitude:	117° 53' 30"	Requester:	Derek Pohle @ (509) 397-6206	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$607,360.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>6/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$607,360.00	Preliminary Engineering:	1/1/2002	Right of Way:	6/1/2002	Construction Start:	6/1/2003		
Sufficiency Rating:	47.16 SD																														
Bridge Owner Name:	Whitman County																														
Bridge Name:	WASSUM																														
Intersecting:	IMBLER CREEK																														
Strudture ID:	08359700																														
Federal Highway:	Off																														
Latitude:	47° 6' 18"																														
Longitude:	117° 53' 30"																														
Requester:	Derek Pohle @ (509) 397-6206																														
Total Project Costs and Start Dates:																															
Projected Replacement :	\$607,360.00																														
Preliminary Engineering:	1/1/2002																														
Right of Way:	6/1/2002																														
Construction Start:	6/1/2003																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Condition Codes:</td> <td>BridgeNo: 412000012</td> </tr> <tr> <td>Deck:</td> <td>6</td> </tr> <tr> <td>Superstructure:</td> <td>4</td> </tr> <tr> <td>Substructure:</td> <td>5</td> </tr> <tr> <td>Scour:</td> <td>7</td> </tr> <tr> <td>Inventory Rating:</td> <td>20 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>28 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 412000012	Deck:	6	Superstructure:	4	Substructure:	5	Scour:	7	Inventory Rating:	20 HS-20 (Tons)	Operating Rating:	28 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>5</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>3</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	5	Under Clearance:	9	Wate way:	8	Roadway Alignment:	3	Safe Load Capacity:	5		
Condition Codes:	BridgeNo: 412000012																														
Deck:	6																														
Superstructure:	4																														
Substructure:	5																														
Scour:	7																														
Inventory Rating:	20 HS-20 (Tons)																														
Operating Rating:	28 HS-20 (Tons)																														
Adequacy Appraisal Codes:																															
Structural:	4																														
Deck Geometry:	5																														
Under Clearance:	9																														
Wate way:	8																														
Roadway Alignment:	3																														
Safe Load Capacity:	5																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Age and Service Data:</td> <td>Fed Func Class: 09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>20 1988</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>15</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1948 0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> </tr> </table>	Age and Service Data:	Fed Func Class: 09	Main/Appr Material Design:	7 02 0 00	Average Daily Traffic Year:	20 1988	Detour Length (Miles)	15	Year Built and Rebuilt:	1948 0	Historical Significance:	4	Open/Closed/Posted:	A	Number of Utilities:	0	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>63</td> </tr> <tr> <td>Curb to Curb:</td> <td>20</td> </tr> <tr> <td>Square feet of deck::</td> <td>1260</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>20</td> </tr> </table>	Geometric Data:		Bridge Length:	63	Curb to Curb:	20	Square feet of deck::	1260	Number of lanes on:	2	Approach Roadway Width:	20		
Age and Service Data:	Fed Func Class: 09																														
Main/Appr Material Design:	7 02 0 00																														
Average Daily Traffic Year:	20 1988																														
Detour Length (Miles)	15																														
Year Built and Rebuilt:	1948 0																														
Historical Significance:	4																														
Open/Closed/Posted:	A																														
Number of Utilities:	0																														
Geometric Data:																															
Bridge Length:	63																														
Curb to Curb:	20																														
Square feet of deck::	1260																														
Number of lanes on:	2																														
Approach Roadway Width:	20																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Precast Prestressed Concrete Beams</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete foundation</td> </tr> <tr> <td>New Foundn Type:</td> <td>Piling or Spread Footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove structure, place piling, abutments, wingwalls, girders, install guardrail and approaches</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Precast Prestressed Concrete Beams	New Sub Type:	Concrete foundation	New Foundn Type:	Piling or Spread Footings	Proposed work:		Remove structure, place piling, abutments, wingwalls, girders, install guardrail and approaches		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>2400</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$48,600.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$1,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$324,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$175,800.00</td> </tr> <tr> <td>Approach:</td> <td>\$57,960.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	2400	Preliminary Engineering:	\$48,600.00	Right of Way:	\$1,000.00	Construction:	\$324,000.00	Other Projected Costs:	\$175,800.00	Approach:	\$57,960.00				
Agency Replacement Comments:																															
New Super Type:	Precast Prestressed Concrete Beams																														
New Sub Type:	Concrete foundation																														
New Foundn Type:	Piling or Spread Footings																														
Proposed work:																															
Remove structure, place piling, abutments, wingwalls, girders, install guardrail and approaches																															
Agency Replacement Costs:																															
New Square Foot:	2400																														
Preliminary Engineering:	\$48,600.00																														
Right of Way:	\$1,000.00																														
Construction:	\$324,000.00																														
Other Projected Costs:	\$175,800.00																														
Approach:	\$57,960.00																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="10">Technical Committee Comment</td> </tr> <tr> <td colspan="2">Load Capacity</td> <td colspan="2">Bridge Geometrics</td> <td colspan="2">Approach Geometrics</td> <td colspan="2">Bridge Condition</td> <td colspan="2">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td></td> <td>FAIR</td> <td></td> <td>GOOD</td> <td></td> <td>GOOD</td> <td></td> <td>POOR</td> <td></td> </tr> </table>		Technical Committee Comment										Load Capacity		Bridge Geometrics		Approach Geometrics		Bridge Condition		Hydraulics		GOOD		FAIR		GOOD		GOOD		POOR	
Technical Committee Comment																															
Load Capacity		Bridge Geometrics		Approach Geometrics		Bridge Condition		Hydraulics																							
GOOD		FAIR		GOOD		GOOD		POOR																							

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>47.61 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>ST JOHN</td> </tr> <tr> <td>Bridge Name:</td> <td>FRONT STREET</td> </tr> <tr> <td>Intersecting:</td> <td>PLEASANT VALLEY CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08499700</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>47° 5' 28.8"</td> </tr> <tr> <td>Longitude:</td> <td>117° 34' 53.6"</td> </tr> <tr> <td>Requester:</td> <td>Linda Hayes @ (509) 648-3905</td> </tr> </table>	Sufficiency Rating:	47.61 SD	Bridge Owner Name:	ST JOHN	Bridge Name:	FRONT STREET	Intersecting:	PLEASANT VALLEY CREEK	Strudture ID:	08499700	Federal Highway:	On	Latitude:	47° 5' 28.8"	Longitude:	117° 34' 53.6"	Requester:	Linda Hayes @ (509) 648-3905	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$257,494.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>9/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td>1/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2002</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$257,494.00	Preliminary Engineering:	9/1/2001	Right of Way:	1/1/2002	Construction Start:	6/1/2002		
Sufficiency Rating:	47.61 SD																														
Bridge Owner Name:	ST JOHN																														
Bridge Name:	FRONT STREET																														
Intersecting:	PLEASANT VALLEY CREEK																														
Strudture ID:	08499700																														
Federal Highway:	On																														
Latitude:	47° 5' 28.8"																														
Longitude:	117° 34' 53.6"																														
Requester:	Linda Hayes @ (509) 648-3905																														
Total Project Costs and Start Dates:																															
Projected Replacement :	\$257,494.00																														
Preliminary Engineering:	9/1/2001																														
Right of Way:	1/1/2002																														
Construction Start:	6/1/2002																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Condition Codes:</td> </tr> <tr> <td>BridgeNo:</td> <td>ST JOHN 2</td> </tr> <tr> <td>Deck:</td> <td>9</td> </tr> <tr> <td>Superstructure:</td> <td>5</td> </tr> <tr> <td>Substructure:</td> <td>4</td> </tr> <tr> <td>Scour:</td> <td>3</td> </tr> <tr> <td>Inventory Rating:</td> <td>32 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>53 HS-20 (Tons)</td> </tr> </table>	Condition Codes:		BridgeNo:	ST JOHN 2	Deck:	9	Superstructure:	5	Substructure:	4	Scour:	3	Inventory Rating:	32 HS-20 (Tons)	Operating Rating:	53 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>6</td> </tr> <tr> <td>Roadway Alignment:</td> <td>3</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	2	Under Clearance:	9	Wate way:	6	Roadway Alignment:	3	Safe Load Capacity:	5
Condition Codes:																															
BridgeNo:	ST JOHN 2																														
Deck:	9																														
Superstructure:	5																														
Substructure:	4																														
Scour:	3																														
Inventory Rating:	32 HS-20 (Tons)																														
Operating Rating:	53 HS-20 (Tons)																														
Adequacy Appraisal Codes:																															
Structural:	4																														
Deck Geometry:	2																														
Under Clearance:	9																														
Wate way:	6																														
Roadway Alignment:	3																														
Safe Load Capacity:	5																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Age and Service Data:</td> </tr> <tr> <td>Fed Func Class:</td> <td>17</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>1 11 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>712 1994</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>1</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1910 0</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> </tr> </table>	Age and Service Data:		Fed Func Class:	17	Main/Appr Material Design:	1 11 0 00	Average Daily Traffic Year:	712 1994	Detour Length (Miles)	1	Year Built and Rebuilt:	1910 0	Historical Significance:	5	Open/Closed/Posted:	A	Number of Utilities:	1	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>32</td> </tr> <tr> <td>Curb to Curb:</td> <td>19.7</td> </tr> <tr> <td>Square feet of deck::</td> <td>630.400024</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>30</td> </tr> </table>	Geometric Data:		Bridge Length:	32	Curb to Curb:	19.7	Square feet of deck::	630.400024	Number of lanes on:	2	Approach Roadway Width:	30
Age and Service Data:																															
Fed Func Class:	17																														
Main/Appr Material Design:	1 11 0 00																														
Average Daily Traffic Year:	712 1994																														
Detour Length (Miles)	1																														
Year Built and Rebuilt:	1910 0																														
Historical Significance:	5																														
Open/Closed/Posted:	A																														
Number of Utilities:	1																														
Geometric Data:																															
Bridge Length:	32																														
Curb to Curb:	19.7																														
Square feet of deck::	630.400024																														
Number of lanes on:	2																														
Approach Roadway Width:	30																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete Beams</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Piles or Spreads Footing</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Remove structure, place piling, abutment, wingwalls, girders, install guardrail and approaches.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Beams	New Sub Type:	Concrete Abutments	New Foundn Type:	Piles or Spreads Footing	Proposed work:		Remove structure, place piling, abutment, wingwalls, girders, install guardrail and approaches.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>640</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$20,736.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$2,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$138,240.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$72,208.00</td> </tr> <tr> <td>Approach:</td> <td>\$24,310.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	640	Preliminary Engineering:	\$20,736.00	Right of Way:	\$2,000.00	Construction:	\$138,240.00	Other Projected Costs:	\$72,208.00	Approach:	\$24,310.00				
Agency Replacement Comments:																															
New Super Type:	Prestressed Concrete Beams																														
New Sub Type:	Concrete Abutments																														
New Foundn Type:	Piles or Spreads Footing																														
Proposed work:																															
Remove structure, place piling, abutment, wingwalls, girders, install guardrail and approaches.																															
Agency Replacement Costs:																															
New Square Foot:	640																														
Preliminary Engineering:	\$20,736.00																														
Right of Way:	\$2,000.00																														
Construction:	\$138,240.00																														
Other Projected Costs:	\$72,208.00																														
Approach:	\$24,310.00																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td>Load Capacity</td> <td>Bridge Geometrics</td> <td>Approach Geometrics</td> <td>Bridge Condition</td> <td>Hydraulics</td> </tr> <tr> <td>FAIR</td> <td>GOOD</td> <td>GOOD</td> <td>GOOD</td> <td>FAIR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	FAIR	GOOD	GOOD	GOOD	FAIR															
Technical Committee Comment																															
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																											
FAIR	GOOD	GOOD	GOOD	FAIR																											

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Sufficiency Rating:</td> <td>47.84 FO</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Lewis County</td> </tr> <tr> <td>Bridge Name:</td> <td>GARNET</td> </tr> <tr> <td>Intersecting:</td> <td>TILTON RIVER</td> </tr> <tr> <td>Strudture ID:</td> <td>08442700</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>46° 34' 18" N</td> </tr> <tr> <td>Longitude:</td> <td>122° 18' 54" W</td> </tr> <tr> <td>Requester:</td> <td>William Frare @ (360) 740-1175</td> </tr> </table>	Sufficiency Rating:	47.84 FO	Bridge Owner Name:	Lewis County	Bridge Name:	GARNET	Intersecting:	TILTON RIVER	Strudture ID:	08442700	Federal Highway:	Off	Latitude:	46° 34' 18" N	Longitude:	122° 18' 54" W	Requester:	William Frare @ (360) 740-1175	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$458,125.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>7/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>7/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$458,125.00	Preliminary Engineering:	1/1/2002	Right of Way:	7/1/2002	Construction Start:	7/1/2003
Sufficiency Rating:	47.84 FO																												
Bridge Owner Name:	Lewis County																												
Bridge Name:	GARNET																												
Intersecting:	TILTON RIVER																												
Strudture ID:	08442700																												
Federal Highway:	Off																												
Latitude:	46° 34' 18" N																												
Longitude:	122° 18' 54" W																												
Requester:	William Frare @ (360) 740-1175																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$458,125.00																												
Preliminary Engineering:	1/1/2002																												
Right of Way:	7/1/2002																												
Construction Start:	7/1/2003																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Condition Codes:</td> <td>BridgeNo: 210000001</td> </tr> <tr> <td>Deck:</td> <td>7</td> </tr> <tr> <td>Superstructure:</td> <td>5</td> </tr> <tr> <td>Substructure:</td> <td>7</td> </tr> <tr> <td>Scour:</td> <td>8</td> </tr> <tr> <td>Inventory Rating:</td> <td>30 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>41 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 210000001	Deck:	7	Superstructure:	5	Substructure:	7	Scour:	8	Inventory Rating:	30 HS-20 (Tons)	Operating Rating:	41 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>5</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>3</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	5	Deck Geometry:	2	Under Clearance:	9	Wate way:	8	Roadway Alignment:	3	Safe Load Capacity:	5
Condition Codes:	BridgeNo: 210000001																												
Deck:	7																												
Superstructure:	5																												
Substructure:	7																												
Scour:	8																												
Inventory Rating:	30 HS-20 (Tons)																												
Operating Rating:	41 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	5																												
Deck Geometry:	2																												
Under Clearance:	9																												
Wate way:	8																												
Roadway Alignment:	3																												
Safe Load Capacity:	5																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Age and Service Data:</td> <td>Fed Func Class: 09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>3 10 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>166 1995</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>99</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1924 1964</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> </tr> </table>	Age and Service Data:	Fed Func Class: 09	Main/Appr Material Design:	3 10 0 00	Average Daily Traffic Year:	166 1995	Detour Length (Miles)	99	Year Built and Rebuilt:	1924 1964	Historical Significance:	5	Open/Closed/Posted:	A	Number of Utilities:	0	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>101</td> </tr> <tr> <td>Curb to Curb:</td> <td>17</td> </tr> <tr> <td>Square feet of deck::</td> <td>1717</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>28</td> </tr> </table>	Geometric Data:		Bridge Length:	101	Curb to Curb:	17	Square feet of deck::	1717	Number of lanes on:	2	Approach Roadway Width:	28
Age and Service Data:	Fed Func Class: 09																												
Main/Appr Material Design:	3 10 0 00																												
Average Daily Traffic Year:	166 1995																												
Detour Length (Miles)	99																												
Year Built and Rebuilt:	1924 1964																												
Historical Significance:	5																												
Open/Closed/Posted:	A																												
Number of Utilities:	0																												
Geometric Data:																													
Bridge Length:	101																												
Curb to Curb:	17																												
Square feet of deck::	1717																												
Number of lanes on:	2																												
Approach Roadway Width:	28																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete Girder</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Concrete Piles</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Install detour, remove existing bridge, construct prestressed concrete girder bridge on concrete pile supported abutments.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Girder	New Sub Type:	Concrete Abutments	New Foundn Type:	Concrete Piles	Proposed work:		Install detour, remove existing bridge, construct prestressed concrete girder bridge on concrete pile supported abutments.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>3080</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$33,750.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$15,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$225,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$141,250.00</td> </tr> <tr> <td>Approach:</td> <td>\$43,125.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	3080	Preliminary Engineering:	\$33,750.00	Right of Way:	\$15,000.00	Construction:	\$225,000.00	Other Projected Costs:	\$141,250.00	Approach:	\$43,125.00		
Agency Replacement Comments:																													
New Super Type:	Prestressed Concrete Girder																												
New Sub Type:	Concrete Abutments																												
New Foundn Type:	Concrete Piles																												
Proposed work:																													
Install detour, remove existing bridge, construct prestressed concrete girder bridge on concrete pile supported abutments.																													
Agency Replacement Costs:																													
New Square Foot:	3080																												
Preliminary Engineering:	\$33,750.00																												
Right of Way:	\$15,000.00																												
Construction:	\$225,000.00																												
Other Projected Costs:	\$141,250.00																												
Approach:	\$43,125.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td>Load Capacity</td> <td>Bridge Geometrics</td> <td>Approach Geometrics</td> <td>Bridge Condition</td> <td>Hydraulics</td> </tr> <tr> <td>FAIR</td> <td>GOOD</td> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	FAIR	GOOD	GOOD	FAIR	POOR													
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
FAIR	GOOD	GOOD	FAIR	POOR																									

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>47.97 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Lincoln County</td> </tr> <tr> <td>Bridge Name:</td> <td>EAST PFIEFER BRIDGE</td> </tr> <tr> <td>Intersecting:</td> <td>CANNAWAI CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08075300</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 30' 54" N</td> </tr> <tr> <td>Longitude:</td> <td>118° 56' 42" W</td> </tr> <tr> <td>Requester:</td> <td>Rick Becker @ (509) 725-7041</td> </tr> </table>	Sufficiency Rating:	47.97 SD	Bridge Owner Name:	Lincoln County	Bridge Name:	EAST PFIEFER BRIDGE	Intersecting:	CANNAWAI CREEK	Strudture ID:	08075300	Federal Highway:	Off	Latitude:	47° 30' 54" N	Longitude:	118° 56' 42" W	Requester:	Rick Becker @ (509) 725-7041	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$298,950.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>3/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>5/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$298,950.00	Preliminary Engineering:	3/1/2002	Right of Way:		Construction Start:	5/1/2003
Sufficiency Rating:	47.97 SD																												
Bridge Owner Name:	Lincoln County																												
Bridge Name:	EAST PFIEFER BRIDGE																												
Intersecting:	CANNAWAI CREEK																												
Strudture ID:	08075300																												
Federal Highway:	Off																												
Latitude:	47° 30' 54" N																												
Longitude:	118° 56' 42" W																												
Requester:	Rick Becker @ (509) 725-7041																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$298,950.00																												
Preliminary Engineering:	3/1/2002																												
Right of Way:																													
Construction Start:	5/1/2003																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Condition Codes:</td> <td>BridgeNo: B-31081</td> </tr> <tr> <td>Deck:</td> <td>7</td> </tr> <tr> <td>Superstructure:</td> <td>7</td> </tr> <tr> <td>Substructure:</td> <td>4</td> </tr> <tr> <td>Scour:</td> <td>5</td> </tr> <tr> <td>Inventory Rating:</td> <td>17 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>28 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: B-31081	Deck:	7	Superstructure:	7	Substructure:	4	Scour:	5	Inventory Rating:	17 HS-20 (Tons)	Operating Rating:	28 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>4</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>7</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>2</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	4	Under Clearance:	9	Wate way:	8	Roadway Alignment:	7	Safe Load Capacity:	2
Condition Codes:	BridgeNo: B-31081																												
Deck:	7																												
Superstructure:	7																												
Substructure:	4																												
Scour:	5																												
Inventory Rating:	17 HS-20 (Tons)																												
Operating Rating:	28 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	4																												
Deck Geometry:	4																												
Under Clearance:	9																												
Wate way:	8																												
Roadway Alignment:	7																												
Safe Load Capacity:	2																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Age and Service Data:</td> <td>Fed Func Class: 09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>3 02 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>23 1990</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>5</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1930 0</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> </tr> </table>	Age and Service Data:	Fed Func Class: 09	Main/Appr Material Design:	3 02 0 00	Average Daily Traffic Year:	23 1990	Detour Length (Miles)	5	Year Built and Rebuilt:	1930 0	Historical Significance:	5	Open/Closed/Posted:	P	Number of Utilities:	0	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>39</td> </tr> <tr> <td>Curb to Curb:</td> <td>18.4</td> </tr> <tr> <td>Square feet of deck::</td> <td>717.599976</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>20</td> </tr> </table>	Geometric Data:		Bridge Length:	39	Curb to Curb:	18.4	Square feet of deck::	717.599976	Number of lanes on:	2	Approach Roadway Width:	20
Age and Service Data:	Fed Func Class: 09																												
Main/Appr Material Design:	3 02 0 00																												
Average Daily Traffic Year:	23 1990																												
Detour Length (Miles)	5																												
Year Built and Rebuilt:	1930 0																												
Historical Significance:	5																												
Open/Closed/Posted:	P																												
Number of Utilities:	0																												
Geometric Data:																													
Bridge Length:	39																												
Curb to Curb:	18.4																												
Square feet of deck::	717.599976																												
Number of lanes on:	2																												
Approach Roadway Width:	20																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Bottomless Arch Multiplate Culvert</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Abutment walls</td> </tr> <tr> <td>New Foundn Type:</td> <td>Concrete Footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">A detour, removing existing structure. Construct footings and abutment walls. Install culvert, bridge approaches, resurface with crushed surfacing</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Bottomless Arch Multiplate Culvert	New Sub Type:	Concrete Abutment walls	New Foundn Type:	Concrete Footings	Proposed work:		A detour, removing existing structure. Construct footings and abutment walls. Install culvert, bridge approaches, resurface with crushed surfacing		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>1740</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$19,500.00</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction:</td> <td>\$130,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$123,500.00</td> </tr> <tr> <td>Approach:</td> <td>\$25,950.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	1740	Preliminary Engineering:	\$19,500.00	Right of Way:		Construction:	\$130,000.00	Other Projected Costs:	\$123,500.00	Approach:	\$25,950.00		
Agency Replacement Comments:																													
New Super Type:	Bottomless Arch Multiplate Culvert																												
New Sub Type:	Concrete Abutment walls																												
New Foundn Type:	Concrete Footings																												
Proposed work:																													
A detour, removing existing structure. Construct footings and abutment walls. Install culvert, bridge approaches, resurface with crushed surfacing																													
Agency Replacement Costs:																													
New Square Foot:	1740																												
Preliminary Engineering:	\$19,500.00																												
Right of Way:																													
Construction:	\$130,000.00																												
Other Projected Costs:	\$123,500.00																												
Approach:	\$25,950.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>FAIR</td> <td>GOOD</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	FAIR	GOOD	POOR													
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
GOOD	FAIR	FAIR	GOOD	POOR																									

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>49.13 FO</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Skamania County</td> </tr> <tr> <td>Bridge Name:</td> <td>BUTLER EDDY BRIDGE</td> </tr> <tr> <td>Intersecting:</td> <td>BUTLER SLOUGH</td> </tr> <tr> <td>Strudture ID:</td> <td>08474400</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>45° 37' 6" Longitude: 122° 2' 30"</td> </tr> <tr> <td>Requester:</td> <td>Forrest Robbins @ (509) 427-9448</td> </tr> </table>	Sufficiency Rating:	49.13 FO	Bridge Owner Name:	Skamania County	Bridge Name:	BUTLER EDDY BRIDGE	Intersecting:	BUTLER SLOUGH	Strudture ID:	08474400	Federal Highway:	Off	Latitude:	45° 37' 6" Longitude: 122° 2' 30"	Requester:	Forrest Robbins @ (509) 427-9448	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$529,500.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>1/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>7/1/2001</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$529,500.00	Preliminary Engineering:	1/1/2001	Right of Way:		Construction Start:	7/1/2001										
Sufficiency Rating:	49.13 FO																																				
Bridge Owner Name:	Skamania County																																				
Bridge Name:	BUTLER EDDY BRIDGE																																				
Intersecting:	BUTLER SLOUGH																																				
Strudture ID:	08474400																																				
Federal Highway:	Off																																				
Latitude:	45° 37' 6" Longitude: 122° 2' 30"																																				
Requester:	Forrest Robbins @ (509) 427-9448																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$529,500.00																																				
Preliminary Engineering:	1/1/2001																																				
Right of Way:																																					
Construction Start:	7/1/2001																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Condition Codes:</td> <td>BridgeNo:</td> <td>106</td> </tr> <tr> <td>Deck:</td> <td>7</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>7</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>6</td> <td></td> </tr> <tr> <td>Scour:</td> <td>8</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>16</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>23</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	106	Deck:	7		Superstructure:	7		Substructure:	6		Scour:	8		Inventory Rating:	16	HS-20 (Tons)	Operating Rating:	23	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>4</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>7</td> </tr> <tr> <td>Roadway Alignment:</td> <td>3</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	4	Under Clearance:	9	Wate way:	7	Roadway Alignment:	3	Safe Load Capacity:	5	
Condition Codes:	BridgeNo:	106																																			
Deck:	7																																				
Superstructure:	7																																				
Substructure:	6																																				
Scour:	8																																				
Inventory Rating:	16	HS-20 (Tons)																																			
Operating Rating:	23	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	4																																				
Deck Geometry:	4																																				
Under Clearance:	9																																				
Wate way:	7																																				
Roadway Alignment:	3																																				
Safe Load Capacity:	5																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>79</td> <td>1999</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>1</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1948</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	09	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	79	1999	Detour Length (Miles)	1		Year Built and Rebuilt:	1948	0	Historical Significance:	4		Open/Closed/Posted:	A		Number of Utilities:	0		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>165</td> </tr> <tr> <td>Curb to Curb:</td> <td>12</td> </tr> <tr> <td>Square feet of deck::</td> <td>1980</td> </tr> <tr> <td>Number of lanes on:</td> <td>1</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>22</td> </tr> </table>	Geometric Data:		Bridge Length:	165	Curb to Curb:	12	Square feet of deck::	1980	Number of lanes on:	1	Approach Roadway Width:	22
Age and Service Data:	Fed Func Class:	09																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	79	1999																																			
Detour Length (Miles)	1																																				
Year Built and Rebuilt:	1948	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	A																																				
Number of Utilities:	0																																				
Geometric Data:																																					
Bridge Length:	165																																				
Curb to Curb:	12																																				
Square feet of deck::	1980																																				
Number of lanes on:	1																																				
Approach Roadway Width:	22																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed Concrete Girders or Slab</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2" style="height: 40px; vertical-align: top;">Remove and replace existing structure.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Girders or Slab	New Sub Type:	Concrete	New Foundn Type:		Proposed work:		Remove and replace existing structure.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>3984</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$45,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$300,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$135,000.00</td> </tr> <tr> <td>Approach:</td> <td>\$49,500.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	3984	Preliminary Engineering:	\$45,000.00	Right of Way:	\$0.00	Construction:	\$300,000.00	Other Projected Costs:	\$135,000.00	Approach:	\$49,500.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed Concrete Girders or Slab																																				
New Sub Type:	Concrete																																				
New Foundn Type:																																					
Proposed work:																																					
Remove and replace existing structure.																																					
Agency Replacement Costs:																																					
New Square Foot:	3984																																				
Preliminary Engineering:	\$45,000.00																																				
Right of Way:	\$0.00																																				
Construction:	\$300,000.00																																				
Other Projected Costs:	\$135,000.00																																				
Approach:	\$49,500.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>FAIR</td> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	FAIR	GOOD	FAIR	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	FAIR	GOOD	FAIR	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>49.37 FO</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Pierce County</td> </tr> <tr> <td>Bridge Name:</td> <td>PUYALLUP RIVER</td> </tr> <tr> <td>Intersecting:</td> <td>PUYALLUP RIVER</td> </tr> <tr> <td>Strudture ID:</td> <td>08235500</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>47° 12' 54" N</td> </tr> <tr> <td>Longitude:</td> <td>122° 20' 24" W</td> </tr> <tr> <td>Requester:</td> <td>Don Peterson @ (253) 798-3147</td> </tr> </table>	Sufficiency Rating:	49.37 FO	Bridge Owner Name:	Pierce County	Bridge Name:	PUYALLUP RIVER	Intersecting:	PUYALLUP RIVER	Strudture ID:	08235500	Federal Highway:	On	Latitude:	47° 12' 54" N	Longitude:	122° 20' 24" W	Requester:	Don Peterson @ (253) 798-3147	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$9,851,000.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td>6/1/2003</td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2004</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$9,851,000.00	Preliminary Engineering:	6/1/2001	Right of Way:	6/1/2003	Construction Start:	6/1/2004								
Sufficiency Rating:	49.37 FO																																				
Bridge Owner Name:	Pierce County																																				
Bridge Name:	PUYALLUP RIVER																																				
Intersecting:	PUYALLUP RIVER																																				
Strudture ID:	08235500																																				
Federal Highway:	On																																				
Latitude:	47° 12' 54" N																																				
Longitude:	122° 20' 24" W																																				
Requester:	Don Peterson @ (253) 798-3147																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$9,851,000.00																																				
Preliminary Engineering:	6/1/2001																																				
Right of Way:	6/1/2003																																				
Construction Start:	6/1/2004																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>18204A</td> </tr> <tr> <td>Deck:</td> <td>6</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>6</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>6</td> <td></td> </tr> <tr> <td>Scour:</td> <td>5</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>20</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>33</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	18204A	Deck:	6		Superstructure:	6		Substructure:	6		Scour:	5		Inventory Rating:	20	HS-20 (Tons)	Operating Rating:	33	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>3</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>2</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	2	Under Clearance:	9	Wate way:	8	Roadway Alignment:	3	Safe Load Capacity:	2	
Condition Codes:	BridgeNo:	18204A																																			
Deck:	6																																				
Superstructure:	6																																				
Substructure:	6																																				
Scour:	5																																				
Inventory Rating:	20	HS-20 (Tons)																																			
Operating Rating:	33	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	4																																				
Deck Geometry:	2																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	3																																				
Safe Load Capacity:	2																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>16</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>3 10</td> <td>3 02</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>10400</td> <td>1999</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>5</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1931</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>B</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	16	Main/Appr Material Design:	3 10	3 02	Average Daily Traffic Year:	10400	1999	Detour Length (Miles)	5		Year Built and Rebuilt:	1931	0	Historical Significance:	5		Open/Closed/Posted:	B		Number of Utilities:	0		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>345</td> </tr> <tr> <td>Curb to Curb:</td> <td>20</td> </tr> <tr> <td>Square feet of deck::</td> <td>6900</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>26</td> </tr> </table>	Geometric Data:		Bridge Length:	345	Curb to Curb:	20	Square feet of deck::	6900	Number of lanes on:	2	Approach Roadway Width:	26
Age and Service Data:	Fed Func Class:	16																																			
Main/Appr Material Design:	3 10	3 02																																			
Average Daily Traffic Year:	10400	1999																																			
Detour Length (Miles)	5																																				
Year Built and Rebuilt:	1931	0																																			
Historical Significance:	5																																				
Open/Closed/Posted:	B																																				
Number of Utilities:	0																																				
Geometric Data:																																					
Bridge Length:	345																																				
Curb to Curb:	20																																				
Square feet of deck::	6900																																				
Number of lanes on:	2																																				
Approach Roadway Width:	26																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Steel Truss</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Walls</td> </tr> <tr> <td>New Foundn Type:</td> <td>Pile Foundation</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2"> Replace existing steel through truss with a new steel bridge on a new alignment. 4-12" lanes, 1-12' turn lane, 2-5' bicycle lanes, 2-6' sidewalks. </td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Steel Truss	New Sub Type:	Concrete Walls	New Foundn Type:	Pile Foundation	Proposed work:		Replace existing steel through truss with a new steel bridge on a new alignment. 4-12" lanes, 1-12' turn lane, 2-5' bicycle lanes, 2-6' sidewalks.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>6900</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$1,139,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$295,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$4,892,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$2,718,000.00</td> </tr> <tr> <td>Approach:</td> <td>\$807,000.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	6900	Preliminary Engineering:	\$1,139,000.00	Right of Way:	\$295,000.00	Construction:	\$4,892,000.00	Other Projected Costs:	\$2,718,000.00	Approach:	\$807,000.00										
Agency Replacement Comments:																																					
New Super Type:	Steel Truss																																				
New Sub Type:	Concrete Walls																																				
New Foundn Type:	Pile Foundation																																				
Proposed work:																																					
Replace existing steel through truss with a new steel bridge on a new alignment. 4-12" lanes, 1-12' turn lane, 2-5' bicycle lanes, 2-6' sidewalks.																																					
Agency Replacement Costs:																																					
New Square Foot:	6900																																				
Preliminary Engineering:	\$1,139,000.00																																				
Right of Way:	\$295,000.00																																				
Construction:	\$4,892,000.00																																				
Other Projected Costs:	\$2,718,000.00																																				
Approach:	\$807,000.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>GOOD</td> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	GOOD	GOOD	FAIR	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	GOOD	GOOD	FAIR	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>49.53 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Walla Walla County</td> </tr> <tr> <td>Bridge Name:</td> <td>HERRING</td> </tr> <tr> <td>Intersecting:</td> <td>COLVILLE GULCH</td> </tr> <tr> <td>Strudture ID:</td> <td>08313300</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>46° 20' 6" Longitude: 118° 15' 36"</td> </tr> <tr> <td>Requester:</td> <td>David Eids @ (509) 527-3241</td> </tr> </table>	Sufficiency Rating:	49.53 SD	Bridge Owner Name:	Walla Walla County	Bridge Name:	HERRING	Intersecting:	COLVILLE GULCH	Strudture ID:	08313300	Federal Highway:	On	Latitude:	46° 20' 6" Longitude: 118° 15' 36"	Requester:	David Eids @ (509) 527-3241	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$562,850.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>6/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td>6/1/2003</td> </tr> <tr> <td>Construction Start:</td> <td>7/1/2004</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$562,850.00	Preliminary Engineering:	6/1/2002	Right of Way:	6/1/2003	Construction Start:	7/1/2004				
Sufficiency Rating:	49.53 SD																														
Bridge Owner Name:	Walla Walla County																														
Bridge Name:	HERRING																														
Intersecting:	COLVILLE GULCH																														
Strudture ID:	08313300																														
Federal Highway:	On																														
Latitude:	46° 20' 6" Longitude: 118° 15' 36"																														
Requester:	David Eids @ (509) 527-3241																														
Total Project Costs and Start Dates:																															
Projected Replacement :	\$562,850.00																														
Preliminary Engineering:	6/1/2002																														
Right of Way:	6/1/2003																														
Construction Start:	7/1/2004																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Condition Codes:</td> <td>BridgeNo: 942500012</td> </tr> <tr> <td>Deck:</td> <td>9</td> </tr> <tr> <td>Superstructure:</td> <td>7</td> </tr> <tr> <td>Substructure:</td> <td>4</td> </tr> <tr> <td>Scour:</td> <td>4</td> </tr> <tr> <td>Inventory Rating:</td> <td>36 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>36 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 942500012	Deck:	9	Superstructure:	7	Substructure:	4	Scour:	4	Inventory Rating:	36 HS-20 (Tons)	Operating Rating:	36 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>3</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>5</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	3	Under Clearance:	9	Wate way:	5	Roadway Alignment:	8	Safe Load Capacity:	5		
Condition Codes:	BridgeNo: 942500012																														
Deck:	9																														
Superstructure:	7																														
Substructure:	4																														
Scour:	4																														
Inventory Rating:	36 HS-20 (Tons)																														
Operating Rating:	36 HS-20 (Tons)																														
Adequacy Appraisal Codes:																															
Structural:	4																														
Deck Geometry:	3																														
Under Clearance:	9																														
Wate way:	5																														
Roadway Alignment:	8																														
Safe Load Capacity:	5																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>Age and Service Data:</td> <td>Fed Func Class: 07</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>1 11 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>150 1997</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>18</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1922 0</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> </tr> </table>	Age and Service Data:	Fed Func Class: 07	Main/Appr Material Design:	1 11 0 00	Average Daily Traffic Year:	150 1997	Detour Length (Miles)	18	Year Built and Rebuilt:	1922 0	Historical Significance:	5	Open/Closed/Posted:	A	Number of Utilities:	0	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>51</td> </tr> <tr> <td>Curb to Curb:</td> <td>19.1</td> </tr> <tr> <td>Square feet of deck::</td> <td>974.100037</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>19</td> </tr> </table>	Geometric Data:		Bridge Length:	51	Curb to Curb:	19.1	Square feet of deck::	974.100037	Number of lanes on:	2	Approach Roadway Width:	19		
Age and Service Data:	Fed Func Class: 07																														
Main/Appr Material Design:	1 11 0 00																														
Average Daily Traffic Year:	150 1997																														
Detour Length (Miles)	18																														
Year Built and Rebuilt:	1922 0																														
Historical Significance:	5																														
Open/Closed/Posted:	A																														
Number of Utilities:	0																														
Geometric Data:																															
Bridge Length:	51																														
Curb to Curb:	19.1																														
Square feet of deck::	974.100037																														
Number of lanes on:	2																														
Approach Roadway Width:	19																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Deck Bulb-t Girder</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Spread Footings</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Replace existing concrete arch with a single span precast bridge. Install guardrail and concrete approach slabs. Reconstruct roadway</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Deck Bulb-t Girder	New Sub Type:	Concrete abutments	New Foundn Type:	Spread Footings	Proposed work:		Replace existing concrete arch with a single span precast bridge. Install guardrail and concrete approach slabs. Reconstruct roadway		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>2720</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$43,500.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$5,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$290,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$170,500.00</td> </tr> <tr> <td>Approach:</td> <td>\$53,850.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	2720	Preliminary Engineering:	\$43,500.00	Right of Way:	\$5,000.00	Construction:	\$290,000.00	Other Projected Costs:	\$170,500.00	Approach:	\$53,850.00				
Agency Replacement Comments:																															
New Super Type:	Deck Bulb-t Girder																														
New Sub Type:	Concrete abutments																														
New Foundn Type:	Spread Footings																														
Proposed work:																															
Replace existing concrete arch with a single span precast bridge. Install guardrail and concrete approach slabs. Reconstruct roadway																															
Agency Replacement Costs:																															
New Square Foot:	2720																														
Preliminary Engineering:	\$43,500.00																														
Right of Way:	\$5,000.00																														
Construction:	\$290,000.00																														
Other Projected Costs:	\$170,500.00																														
Approach:	\$53,850.00																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="10">Technical Committee Comment</td> </tr> <tr> <td colspan="2">Load Capacity</td> <td colspan="2">Bridge Geometrics</td> <td colspan="2">Approach Geometrics</td> <td colspan="2">Bridge Condition</td> <td colspan="2">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td></td> <td>FAIR</td> <td></td> <td>POOR</td> <td></td> <td>GOOD</td> <td></td> <td>POOR</td> <td></td> </tr> </table>		Technical Committee Comment										Load Capacity		Bridge Geometrics		Approach Geometrics		Bridge Condition		Hydraulics		GOOD		FAIR		POOR		GOOD		POOR	
Technical Committee Comment																															
Load Capacity		Bridge Geometrics		Approach Geometrics		Bridge Condition		Hydraulics																							
GOOD		FAIR		POOR		GOOD		POOR																							

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>49.62 FO</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Pierce County</td> </tr> <tr> <td>Bridge Name:</td> <td>S FORK MUCK CREEK</td> </tr> <tr> <td>Intersecting:</td> <td>S FORK MUCK CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08137800</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>46° 58' 48" N</td> </tr> <tr> <td>Longitude:</td> <td>122° 22' 12" W</td> </tr> <tr> <td>Requester:</td> <td>Don Peterson @ (253) 798-3147</td> </tr> </table>	Sufficiency Rating:	49.62 FO	Bridge Owner Name:	Pierce County	Bridge Name:	S FORK MUCK CREEK	Intersecting:	S FORK MUCK CREEK	Strudture ID:	08137800	Federal Highway:	On	Latitude:	46° 58' 48" N	Longitude:	122° 22' 12" W	Requester:	Don Peterson @ (253) 798-3147	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$615,000.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>12/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$615,000.00	Preliminary Engineering:	12/1/2001	Right of Way:		Construction Start:	6/1/2003								
Sufficiency Rating:	49.62 FO																																				
Bridge Owner Name:	Pierce County																																				
Bridge Name:	S FORK MUCK CREEK																																				
Intersecting:	S FORK MUCK CREEK																																				
Strudture ID:	08137800																																				
Federal Highway:	On																																				
Latitude:	46° 58' 48" N																																				
Longitude:	122° 22' 12" W																																				
Requester:	Don Peterson @ (253) 798-3147																																				
Total Project Costs and Start Dates:																																					
Projected Replacement :	\$615,000.00																																				
Preliminary Engineering:	12/1/2001																																				
Right of Way:																																					
Construction Start:	6/1/2003																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo:</td> <td>12173B</td> </tr> <tr> <td>Deck:</td> <td>6</td> <td></td> </tr> <tr> <td>Superstructure:</td> <td>5</td> <td></td> </tr> <tr> <td>Substructure:</td> <td>6</td> <td></td> </tr> <tr> <td>Scour:</td> <td>5</td> <td></td> </tr> <tr> <td>Inventory Rating:</td> <td>20</td> <td>HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>38</td> <td>HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo:	12173B	Deck:	6		Superstructure:	5		Substructure:	6		Scour:	5		Inventory Rating:	20	HS-20 (Tons)	Operating Rating:	38	HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>5</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	5	Deck Geometry:	2	Under Clearance:	9	Wate way:	8	Roadway Alignment:	8	Safe Load Capacity:	5	
Condition Codes:	BridgeNo:	12173B																																			
Deck:	6																																				
Superstructure:	5																																				
Substructure:	6																																				
Scour:	5																																				
Inventory Rating:	20	HS-20 (Tons)																																			
Operating Rating:	38	HS-20 (Tons)																																			
Adequacy Appraisal Codes:																																					
Structural:	5																																				
Deck Geometry:	2																																				
Under Clearance:	9																																				
Wate way:	8																																				
Roadway Alignment:	8																																				
Safe Load Capacity:	5																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class:</td> <td>06</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>7 02</td> <td>0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>1350</td> <td>1998</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>11</td> <td></td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1952</td> <td>0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> <td></td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> <td></td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class:	06	Main/Appr Material Design:	7 02	0 00	Average Daily Traffic Year:	1350	1998	Detour Length (Miles)	11		Year Built and Rebuilt:	1952	0	Historical Significance:	4		Open/Closed/Posted:	A		Number of Utilities:	1		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>60</td> </tr> <tr> <td>Curb to Curb:</td> <td>19</td> </tr> <tr> <td>Square feet of deck::</td> <td>1140</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>22</td> </tr> </table>	Geometric Data:		Bridge Length:	60	Curb to Curb:	19	Square feet of deck::	1140	Number of lanes on:	2	Approach Roadway Width:	22
Age and Service Data:	Fed Func Class:	06																																			
Main/Appr Material Design:	7 02	0 00																																			
Average Daily Traffic Year:	1350	1998																																			
Detour Length (Miles)	11																																				
Year Built and Rebuilt:	1952	0																																			
Historical Significance:	4																																				
Open/Closed/Posted:	A																																				
Number of Utilities:	1																																				
Geometric Data:																																					
Bridge Length:	60																																				
Curb to Curb:	19																																				
Square feet of deck::	1140																																				
Number of lanes on:	2																																				
Approach Roadway Width:	22																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Prestressed concrete slabs</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Spread footings or piling</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2"> Replace existing 19' wide, 60' long, two-span timber structure with an 80' long prestressed single span structure with 2-11' lanes and 2-8' shoulders. </td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed concrete slabs	New Sub Type:	Concrete abutments	New Foundn Type:	Spread footings or piling	Proposed work:		Replace existing 19' wide, 60' long, two-span timber structure with an 80' long prestressed single span structure with 2-11' lanes and 2-8' shoulders.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>3040</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$73,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$279,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$217,000.00</td> </tr> <tr> <td>Approach:</td> <td>\$46,000.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	3040	Preliminary Engineering:	\$73,000.00	Right of Way:	\$0.00	Construction:	\$279,000.00	Other Projected Costs:	\$217,000.00	Approach:	\$46,000.00										
Agency Replacement Comments:																																					
New Super Type:	Prestressed concrete slabs																																				
New Sub Type:	Concrete abutments																																				
New Foundn Type:	Spread footings or piling																																				
Proposed work:																																					
Replace existing 19' wide, 60' long, two-span timber structure with an 80' long prestressed single span structure with 2-11' lanes and 2-8' shoulders.																																					
Agency Replacement Costs:																																					
New Square Foot:	3040																																				
Preliminary Engineering:	\$73,000.00																																				
Right of Way:	\$0.00																																				
Construction:	\$279,000.00																																				
Other Projected Costs:	\$217,000.00																																				
Approach:	\$46,000.00																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>GOOD</td> <td>POOR</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	GOOD	POOR	FAIR	POOR																					
Technical Committee Comment																																					
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																																	
GOOD	GOOD	POOR	FAIR	POOR																																	

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>49.71 FO</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Pierce County</td> </tr> <tr> <td>Bridge Name:</td> <td>MASHELL RIVER</td> </tr> <tr> <td>Intersecting:</td> <td>MASHELL RIVER</td> </tr> <tr> <td>Strudture ID:</td> <td>08327100</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>46° 51' 48" Longitude: 122° 15' 6"</td> </tr> <tr> <td>Requester:</td> <td>Don Peterson @ (253) 798-3147</td> </tr> </table>	Sufficiency Rating:	49.71 FO	Bridge Owner Name:	Pierce County	Bridge Name:	MASHELL RIVER	Intersecting:	MASHELL RIVER	Strudture ID:	08327100	Federal Highway:	On	Latitude:	46° 51' 48" Longitude: 122° 15' 6"	Requester:	Don Peterson @ (253) 798-3147	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Total Project Costs and Start Dates:</th> </tr> <tr> <td>Projected Replacement :</td> <td>\$1,515,000.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>12/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td>9/1/2002</td> </tr> <tr> <td>Construction Start:</td> <td>4/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$1,515,000.00	Preliminary Engineering:	12/1/2001	Right of Way:	9/1/2002	Construction Start:	4/1/2003		
Sufficiency Rating:	49.71 FO																												
Bridge Owner Name:	Pierce County																												
Bridge Name:	MASHELL RIVER																												
Intersecting:	MASHELL RIVER																												
Strudture ID:	08327100																												
Federal Highway:	On																												
Latitude:	46° 51' 48" Longitude: 122° 15' 6"																												
Requester:	Don Peterson @ (253) 798-3147																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$1,515,000.00																												
Preliminary Engineering:	12/1/2001																												
Right of Way:	9/1/2002																												
Construction Start:	4/1/2003																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo: 24164A</td> </tr> <tr> <td>Deck:</td> <td>6</td> </tr> <tr> <td>Superstructure:</td> <td>6</td> </tr> <tr> <td>Substructure:</td> <td>7</td> </tr> <tr> <td>Scour:</td> <td>3</td> </tr> <tr> <td>Inventory Rating:</td> <td>18 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>30 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: 24164A	Deck:	6	Superstructure:	6	Substructure:	7	Scour:	3	Inventory Rating:	18 HS-20 (Tons)	Operating Rating:	30 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Adequacy Appraisal Codes:</th> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>2</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	2	Under Clearance:	9	Wate way:	8	Roadway Alignment:	6	Safe Load Capacity:	5
Condition Codes:	BridgeNo: 24164A																												
Deck:	6																												
Superstructure:	6																												
Substructure:	7																												
Scour:	3																												
Inventory Rating:	18 HS-20 (Tons)																												
Operating Rating:	30 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	4																												
Deck Geometry:	2																												
Under Clearance:	9																												
Wate way:	8																												
Roadway Alignment:	6																												
Safe Load Capacity:	5																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class: 06</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>1 05 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>3611 1996</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>15</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1937 0</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td>1</td> </tr> </table>	Age and Service Data:	Fed Func Class: 06	Main/Appr Material Design:	1 05 0 00	Average Daily Traffic Year:	3611 1996	Detour Length (Miles)	15	Year Built and Rebuilt:	1937 0	Historical Significance:	5	Open/Closed/Posted:	A	Number of Utilities:	1	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Geometric Data:</th> </tr> <tr> <td>Bridge Length:</td> <td>162</td> </tr> <tr> <td>Curb to Curb:</td> <td>20</td> </tr> <tr> <td>Square feet of deck::</td> <td>3240</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>32</td> </tr> </table>	Geometric Data:		Bridge Length:	162	Curb to Curb:	20	Square feet of deck::	3240	Number of lanes on:	2	Approach Roadway Width:	32
Age and Service Data:	Fed Func Class: 06																												
Main/Appr Material Design:	1 05 0 00																												
Average Daily Traffic Year:	3611 1996																												
Detour Length (Miles)	15																												
Year Built and Rebuilt:	1937 0																												
Historical Significance:	5																												
Open/Closed/Posted:	A																												
Number of Utilities:	1																												
Geometric Data:																													
Bridge Length:	162																												
Curb to Curb:	20																												
Square feet of deck::	3240																												
Number of lanes on:	2																												
Approach Roadway Width:	32																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Agency Replacement Comments:</th> </tr> <tr> <td style="width: 30%;">New Super Type:</td> <td>Prestressed Concrete Girder</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Piers</td> </tr> <tr> <td>New Foundn Type:</td> <td>Pile Supported</td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2" style="height: 40px; vertical-align: top;"> Remove existing concrete box structure with a new prestressed concrete girder bridge. 2-11' lanes, 2-8' shoulders. Detour bridge would be required </td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Concrete Girder	New Sub Type:	Concrete Piers	New Foundn Type:	Pile Supported	Proposed work:		Remove existing concrete box structure with a new prestressed concrete girder bridge. 2-11' lanes, 2-8' shoulders. Detour bridge would be required		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Agency Replacement Costs:</th> </tr> <tr> <td>New Square Foot:</td> <td>6270</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$171,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$25,000.00</td> </tr> <tr> <td>Construction:</td> <td>\$575,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$612,000.00</td> </tr> <tr> <td>Approach:</td> <td>\$132,000.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	6270	Preliminary Engineering:	\$171,000.00	Right of Way:	\$25,000.00	Construction:	\$575,000.00	Other Projected Costs:	\$612,000.00	Approach:	\$132,000.00		
Agency Replacement Comments:																													
New Super Type:	Prestressed Concrete Girder																												
New Sub Type:	Concrete Piers																												
New Foundn Type:	Pile Supported																												
Proposed work:																													
Remove existing concrete box structure with a new prestressed concrete girder bridge. 2-11' lanes, 2-8' shoulders. Detour bridge would be required																													
Agency Replacement Costs:																													
New Square Foot:	6270																												
Preliminary Engineering:	\$171,000.00																												
Right of Way:	\$25,000.00																												
Construction:	\$575,000.00																												
Other Projected Costs:	\$612,000.00																												
Approach:	\$132,000.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">Technical Committee Comment</th> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>GOOD</td> <td>FAIR</td> <td>FAIR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment		Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	GOOD	FAIR	FAIR	POOR																
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
GOOD	GOOD	FAIR	FAIR	POOR																									

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Sufficiency Rating:</td> <td>49.75 SD</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>Lincoln County</td> </tr> <tr> <td>Bridge Name:</td> <td>G. Kunz Bridge No. 63011</td> </tr> <tr> <td>Intersecting:</td> <td>SHERMAN CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>07974000</td> </tr> <tr> <td>Federal Highway:</td> <td>Off</td> </tr> <tr> <td>Latitude:</td> <td>47° 47' 12" N</td> </tr> <tr> <td>Longitude:</td> <td>118° 36' 42" W</td> </tr> <tr> <td>Requester:</td> <td>Rick Becker @ (509) 725 7041</td> </tr> </table>	Sufficiency Rating:	49.75 SD	Bridge Owner Name:	Lincoln County	Bridge Name:	G. Kunz Bridge No. 63011	Intersecting:	SHERMAN CREEK	Strudture ID:	07974000	Federal Highway:	Off	Latitude:	47° 47' 12" N	Longitude:	118° 36' 42" W	Requester:	Rick Becker @ (509) 725 7041	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$387,100.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>3/1/2002</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>6/1/2003</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$387,100.00	Preliminary Engineering:	3/1/2002	Right of Way:		Construction Start:	6/1/2003		
Sufficiency Rating:	49.75 SD																														
Bridge Owner Name:	Lincoln County																														
Bridge Name:	G. Kunz Bridge No. 63011																														
Intersecting:	SHERMAN CREEK																														
Strudture ID:	07974000																														
Federal Highway:	Off																														
Latitude:	47° 47' 12" N																														
Longitude:	118° 36' 42" W																														
Requester:	Rick Becker @ (509) 725 7041																														
Total Project Costs and Start Dates:																															
Projected Replacement :	\$387,100.00																														
Preliminary Engineering:	3/1/2002																														
Right of Way:																															
Construction Start:	6/1/2003																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Condition Codes:</td> <td>BridgeNo: B-63011</td> </tr> <tr> <td>Deck:</td> <td>6</td> </tr> <tr> <td>Superstructure:</td> <td>6</td> </tr> <tr> <td>Substructure:</td> <td>4</td> </tr> <tr> <td>Scour:</td> <td>3</td> </tr> <tr> <td>Inventory Rating:</td> <td>18 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>27 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: B-63011	Deck:	6	Superstructure:	6	Substructure:	4	Scour:	3	Inventory Rating:	18 HS-20 (Tons)	Operating Rating:	27 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>4</td> </tr> <tr> <td>Deck Geometry:</td> <td>6</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>4</td> </tr> <tr> <td>Roadway Alignment:</td> <td>8</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>4</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	4	Deck Geometry:	6	Under Clearance:	9	Wate way:	4	Roadway Alignment:	8	Safe Load Capacity:	4		
Condition Codes:	BridgeNo: B-63011																														
Deck:	6																														
Superstructure:	6																														
Substructure:	4																														
Scour:	3																														
Inventory Rating:	18 HS-20 (Tons)																														
Operating Rating:	27 HS-20 (Tons)																														
Adequacy Appraisal Codes:																															
Structural:	4																														
Deck Geometry:	6																														
Under Clearance:	9																														
Wate way:	4																														
Roadway Alignment:	8																														
Safe Load Capacity:	4																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Age and Service Data:</td> <td>Fed Func Class: 09</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>3 02 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>27 1992</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>7</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1936 0</td> </tr> <tr> <td>Historical Significance:</td> <td>5</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>P</td> </tr> <tr> <td>Number of Utilities:</td> <td>0</td> </tr> </table>	Age and Service Data:	Fed Func Class: 09	Main/Appr Material Design:	3 02 0 00	Average Daily Traffic Year:	27 1992	Detour Length (Miles)	7	Year Built and Rebuilt:	1936 0	Historical Significance:	5	Open/Closed/Posted:	P	Number of Utilities:	0	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>30</td> </tr> <tr> <td>Curb to Curb:</td> <td>26</td> </tr> <tr> <td>Square feet of deck::</td> <td>780</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>18</td> </tr> </table>	Geometric Data:		Bridge Length:	30	Curb to Curb:	26	Square feet of deck::	780	Number of lanes on:	2	Approach Roadway Width:	18		
Age and Service Data:	Fed Func Class: 09																														
Main/Appr Material Design:	3 02 0 00																														
Average Daily Traffic Year:	27 1992																														
Detour Length (Miles)	7																														
Year Built and Rebuilt:	1936 0																														
Historical Significance:	5																														
Open/Closed/Posted:	P																														
Number of Utilities:	0																														
Geometric Data:																															
Bridge Length:	30																														
Curb to Curb:	26																														
Square feet of deck::	780																														
Number of lanes on:	2																														
Approach Roadway Width:	18																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td style="width: 30%;">New Super Type:</td> <td>Prestressed Precast Girder</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td>Concrete Spread Footing or Piling</td> </tr> <tr> <td colspan="2">Proposed work:</td> </tr> <tr> <td colspan="2">Project will include a detour and removing existing structure. Construction of a new sub and superstructure, bridge approaches and resurface w/crushed surfacing.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Prestressed Precast Girder	New Sub Type:	Concrete Abutments	New Foundn Type:	Concrete Spread Footing or Piling	Proposed work:		Project will include a detour and removing existing structure. Construction of a new sub and superstructure, bridge approaches and resurface w/crushed surfacing.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>1400</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$28,500.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$190,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$130,500.00</td> </tr> <tr> <td>Approach:</td> <td>\$38,100.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	1400	Preliminary Engineering:	\$28,500.00	Right of Way:	\$0.00	Construction:	\$190,000.00	Other Projected Costs:	\$130,500.00	Approach:	\$38,100.00				
Agency Replacement Comments:																															
New Super Type:	Prestressed Precast Girder																														
New Sub Type:	Concrete Abutments																														
New Foundn Type:	Concrete Spread Footing or Piling																														
Proposed work:																															
Project will include a detour and removing existing structure. Construction of a new sub and superstructure, bridge approaches and resurface w/crushed surfacing.																															
Agency Replacement Costs:																															
New Square Foot:	1400																														
Preliminary Engineering:	\$28,500.00																														
Right of Way:	\$0.00																														
Construction:	\$190,000.00																														
Other Projected Costs:	\$130,500.00																														
Approach:	\$38,100.00																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="10">Technical Committee Comment</td> </tr> <tr> <td colspan="2">Load Capacity</td> <td colspan="2">Bridge Geometrics</td> <td colspan="2">Approach Geometrics</td> <td colspan="2">Bridge Condition</td> <td colspan="2">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td></td> <td>POOR</td> <td></td> <td>POOR</td> <td></td> <td>GOOD</td> <td></td> <td>GOOD</td> <td></td> </tr> </table>		Technical Committee Comment										Load Capacity		Bridge Geometrics		Approach Geometrics		Bridge Condition		Hydraulics		GOOD		POOR		POOR		GOOD		GOOD	
Technical Committee Comment																															
Load Capacity		Bridge Geometrics		Approach Geometrics		Bridge Condition		Hydraulics																							
GOOD		POOR		POOR		GOOD		GOOD																							

2001 Spring Replacement Candidates

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Sufficiency Rating:</td> <td>51.01 FO</td> </tr> <tr> <td>Bridge Owner Name:</td> <td>PORT ANGELES</td> </tr> <tr> <td>Bridge Name:</td> <td>LAURIDSEN BLVD</td> </tr> <tr> <td>Intersecting:</td> <td>PEABODY CREEK</td> </tr> <tr> <td>Strudture ID:</td> <td>08514400</td> </tr> <tr> <td>Federal Highway:</td> <td>On</td> </tr> <tr> <td>Latitude:</td> <td>0 ' "</td> </tr> <tr> <td>Longitude:</td> <td>0 ' "</td> </tr> <tr> <td>Requester:</td> <td>Gary W. Kenworthy @ (360) 417-4803</td> </tr> </table>	Sufficiency Rating:	51.01 FO	Bridge Owner Name:	PORT ANGELES	Bridge Name:	LAURIDSEN BLVD	Intersecting:	PEABODY CREEK	Strudture ID:	08514400	Federal Highway:	On	Latitude:	0 ' "	Longitude:	0 ' "	Requester:	Gary W. Kenworthy @ (360) 417-4803	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Total Project Costs and Start Dates:</td> </tr> <tr> <td>Projected Replacement :</td> <td>\$2,816,875.00</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>10/1/2001</td> </tr> <tr> <td>Right of Way:</td> <td></td> </tr> <tr> <td>Construction Start:</td> <td>9/1/2002</td> </tr> </table>	Total Project Costs and Start Dates:		Projected Replacement :	\$2,816,875.00	Preliminary Engineering:	10/1/2001	Right of Way:		Construction Start:	9/1/2002
Sufficiency Rating:	51.01 FO																												
Bridge Owner Name:	PORT ANGELES																												
Bridge Name:	LAURIDSEN BLVD																												
Intersecting:	PEABODY CREEK																												
Strudture ID:	08514400																												
Federal Highway:	On																												
Latitude:	0 ' "																												
Longitude:	0 ' "																												
Requester:	Gary W. Kenworthy @ (360) 417-4803																												
Total Project Costs and Start Dates:																													
Projected Replacement :	\$2,816,875.00																												
Preliminary Engineering:	10/1/2001																												
Right of Way:																													
Construction Start:	9/1/2002																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Condition Codes:</td> <td>BridgeNo: PT ANGL 3</td> </tr> <tr> <td>Deck:</td> <td>7</td> </tr> <tr> <td>Superstructure:</td> <td>7</td> </tr> <tr> <td>Substructure:</td> <td>7</td> </tr> <tr> <td>Scour:</td> <td>9</td> </tr> <tr> <td>Inventory Rating:</td> <td>16 HS-20 (Tons)</td> </tr> <tr> <td>Operating Rating:</td> <td>27 HS-20 (Tons)</td> </tr> </table>	Condition Codes:	BridgeNo: PT ANGL 3	Deck:	7	Superstructure:	7	Substructure:	7	Scour:	9	Inventory Rating:	16 HS-20 (Tons)	Operating Rating:	27 HS-20 (Tons)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Adequacy Appraisal Codes:</td> </tr> <tr> <td>Structural:</td> <td>3</td> </tr> <tr> <td>Deck Geometry:</td> <td>3</td> </tr> <tr> <td>Under Clearance:</td> <td>9</td> </tr> <tr> <td>Wate way:</td> <td>8</td> </tr> <tr> <td>Roadway Alignment:</td> <td>6</td> </tr> <tr> <td>Safe Load Capacity:</td> <td>5</td> </tr> </table>	Adequacy Appraisal Codes:		Structural:	3	Deck Geometry:	3	Under Clearance:	9	Wate way:	8	Roadway Alignment:	6	Safe Load Capacity:	5
Condition Codes:	BridgeNo: PT ANGL 3																												
Deck:	7																												
Superstructure:	7																												
Substructure:	7																												
Scour:	9																												
Inventory Rating:	16 HS-20 (Tons)																												
Operating Rating:	27 HS-20 (Tons)																												
Adequacy Appraisal Codes:																													
Structural:	3																												
Deck Geometry:	3																												
Under Clearance:	9																												
Wate way:	8																												
Roadway Alignment:	6																												
Safe Load Capacity:	5																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Age and Service Data:</td> <td>Fed Func Class: 16</td> </tr> <tr> <td>Main/Appr Material Design:</td> <td>1 01 0 00</td> </tr> <tr> <td>Average Daily Traffic Year:</td> <td>5322 1985</td> </tr> <tr> <td>Detour Length (Miles)</td> <td>1</td> </tr> <tr> <td>Year Built and Rebuilt:</td> <td>1968 0</td> </tr> <tr> <td>Historical Significance:</td> <td>4</td> </tr> <tr> <td>Open/Closed/Posted:</td> <td>A</td> </tr> <tr> <td>Number of Utilities:</td> <td></td> </tr> </table>	Age and Service Data:	Fed Func Class: 16	Main/Appr Material Design:	1 01 0 00	Average Daily Traffic Year:	5322 1985	Detour Length (Miles)	1	Year Built and Rebuilt:	1968 0	Historical Significance:	4	Open/Closed/Posted:	A	Number of Utilities:		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Geometric Data:</td> </tr> <tr> <td>Bridge Length:</td> <td>205</td> </tr> <tr> <td>Curb to Curb:</td> <td>28</td> </tr> <tr> <td>Square feet of deck::</td> <td>5740</td> </tr> <tr> <td>Number of lanes on:</td> <td>2</td> </tr> <tr> <td>Approach Roadway Width:</td> <td>50</td> </tr> </table>	Geometric Data:		Bridge Length:	205	Curb to Curb:	28	Square feet of deck::	5740	Number of lanes on:	2	Approach Roadway Width:	50
Age and Service Data:	Fed Func Class: 16																												
Main/Appr Material Design:	1 01 0 00																												
Average Daily Traffic Year:	5322 1985																												
Detour Length (Miles)	1																												
Year Built and Rebuilt:	1968 0																												
Historical Significance:	4																												
Open/Closed/Posted:	A																												
Number of Utilities:																													
Geometric Data:																													
Bridge Length:	205																												
Curb to Curb:	28																												
Square feet of deck::	5740																												
Number of lanes on:	2																												
Approach Roadway Width:	50																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Comments:</td> </tr> <tr> <td>New Super Type:</td> <td>Precast Concrete Beam</td> </tr> <tr> <td>New Sub Type:</td> <td>Concrete Abutments</td> </tr> <tr> <td>New Foundn Type:</td> <td></td> </tr> <tr> <td>Proposed work:</td> <td></td> </tr> <tr> <td colspan="2">Demolition of existing timber bridge and construction of a new concrete bridge in its place.</td> </tr> </table>	Agency Replacement Comments:		New Super Type:	Precast Concrete Beam	New Sub Type:	Concrete Abutments	New Foundn Type:		Proposed work:		Demolition of existing timber bridge and construction of a new concrete bridge in its place.		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Agency Replacement Costs:</td> </tr> <tr> <td>New Square Foot:</td> <td>10250</td> </tr> <tr> <td>Preliminary Engineering:</td> <td>\$192,000.00</td> </tr> <tr> <td>Right of Way:</td> <td>\$0.00</td> </tr> <tr> <td>Construction:</td> <td>\$1,625,000.00</td> </tr> <tr> <td>Other Projected Costs:</td> <td>\$731,250.00</td> </tr> <tr> <td>Approach:</td> <td>\$268,125.00</td> </tr> </table>	Agency Replacement Costs:		New Square Foot:	10250	Preliminary Engineering:	\$192,000.00	Right of Way:	\$0.00	Construction:	\$1,625,000.00	Other Projected Costs:	\$731,250.00	Approach:	\$268,125.00		
Agency Replacement Comments:																													
New Super Type:	Precast Concrete Beam																												
New Sub Type:	Concrete Abutments																												
New Foundn Type:																													
Proposed work:																													
Demolition of existing timber bridge and construction of a new concrete bridge in its place.																													
Agency Replacement Costs:																													
New Square Foot:	10250																												
Preliminary Engineering:	\$192,000.00																												
Right of Way:	\$0.00																												
Construction:	\$1,625,000.00																												
Other Projected Costs:	\$731,250.00																												
Approach:	\$268,125.00																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="5">Technical Committee Comment</td> </tr> <tr> <td style="width: 20%;">Load Capacity</td> <td style="width: 20%;">Bridge Geometrics</td> <td style="width: 20%;">Approach Geometrics</td> <td style="width: 20%;">Bridge Condition</td> <td style="width: 20%;">Hydraulics</td> </tr> <tr> <td>GOOD</td> <td>GOOD</td> <td>FAIR</td> <td>POOR</td> <td>POOR</td> </tr> </table>		Technical Committee Comment					Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics	GOOD	GOOD	FAIR	POOR	POOR													
Technical Committee Comment																													
Load Capacity	Bridge Geometrics	Approach Geometrics	Bridge Condition	Hydraulics																									
GOOD	GOOD	FAIR	POOR	POOR																									